

UREA DELIVERIES  
10/01/11-9/30/12

lbs x .10526

VENDOR	BOL #	DELIVERY DATE	QUANTITY GALLONS
Colonial	209312	10/6/2011	4943
Colonial	209364	10/18/2011	5012
Colonial	209497	11/10/2011	5012
Colonial	209588	11/30/2011	5063
Colonial	209691	12/20/2011	5052
Colonial	209755	1/9/2012	5059
Colonial	209820	1/18/2012	5052
Colonial	209898	2/1/2012	5063
Colonial	210046	2/23/2012	5063
Colonial	210126	3/7/2012	5068
Colonial	210334	4/2/2012	4823



## Rebecca S Macionski

---

**From:** Grondahl, Max <Max.Grondahl@dep.state.fl.us>  
**Sent:** Monday, April 02, 2012 1:06 PM  
**To:** Rebecca S Macionski  
**Subject:** RE: Pinellas County Resource Recovery Facility; 28March2012 MWC Unit #1

**Categories:** Environmental Management, Excess Emission Event FDEP Notification

Hi again Rebecca,

Could you tell me if the #1 south hydraulic pump coupling mentioned below has been repaired or replaced?

Thanks,  
Max

*Please take a few minutes to share your comments on the service you received from the department by clicking on this link. [DEP Customer Survey](#).*

**From:** Rebecca S Macionski [mailto:rebecca.macionski@veoliaes.com]

**Sent:** Thursday, March 29, 2012 4:34 PM

**To:** Grondahl, Max; Henry, Danielle D.

**Cc:** Kelsi Oswald; Robert Hauser; Burns, Beth; Sam G Parker; tstankunas@earthshineinc.com; Bill Crellin; David H Blackmore; Christopher J Neu; Thomas Murphy

**Subject:** RE: Pinellas County Resource Recovery Facility; 28March2012 MWC Unit #1

Hello Max,

On March 28, 2012 at approximately 13:10 hours, MWC Unit #3 was experiencing erratic carbon monoxide levels. In response, the control room operator adjusted the combustion air. The erratic carbon monoxide levels were likely associated with the #1 south hydraulic pump coupling near eminent failure, which was discovered during a vibration level check. This could have affected the amount of hydraulic oil being delivered slowing the Martin grate operation creating a thick combustion fuel bed. Also during this period, MWC Unit #1 was experiencing boiler draft issues which also adversely affected combustion.

MWC Unit #1 recorded a carbon monoxide value of 101 ppm corrected to 7% oxygen for the four hour block average during the period from 12:00 to 15:59 hours.

Please feel free to contact me should you have any questions.

Kind Regards,  
Rebecca

Veolia ES Pinellas, Inc.  
3001 110<sup>th</sup> Avenue North  
Saint Petersburg, FL 33713  
(727) 572-9163



ENVIRONMENTAL SERVICES  
WASTE-TO-ENERGY  
NORTH AMERICA

Excess Emission Notification or Explanation of Carbon/ Continuous Emission Monitor Event/ Discrepancy

<u>Parameter</u>	<u>Permitted Level</u>	<u>Compliance Avg. Period</u>	<u>Circle ALL that Apply</u>	<u>MAGNITUDE</u>
Opacity	10%	6-minute block average	Yes- Enter # of blocks	
Sulfur Dioxide	29 ppm corrected to 7% oxygen	24-hour geometric average	0000-2359	
Carbon Monoxide	100 ppm corrected to 7% oxygen	4-hour block average	0000-0359; 0400-0759; 0800-1159; 1200-1559; 1600-1959; 2000-2359	100
Nitrogen Oxides	205 ppm corrected to 7% oxygen	24-hour block average	0000-2359	
Steam Flow	265 kilo-pounds per hour	4-hour block average	0000-0359; 0400-0759; 0800-1159; 1200-1559; 1600-1959; 2000-2359	
SDA Outlet Temp.	340 degrees Fahrenheit	4-hour block average	0000-0359; 0400-0759; 0800-1159; 1200-1559; 1600-1959; 2000-2359	
Carbon Injection	15 pounds per hour	8-hour period	0000-0759; 0800-1559; 1600-2359	

(\*\*COPY OF CONTROL ROOM LOG BOOK MUST BE ATTACHED TO SIGNED VERSION OF THIS REPORT AND ELECTRONIC VERSION OF THIS FORM MUST BE EMAILED TO ENVIRONMENTAL MANAGER, OPERATIONS SUPERVISOR & MANAGER, AND FACILITY MANAGER\*\*)

EXCESS EMISSION/ CONTINUOUS EMISSION MONITORING SYSTEM EVENT

<u>DATE</u>	<u>UNIT</u>	<u>PARAMETER</u>	<u>EVENT START TIME</u>	<u>EVENT END TIME</u>	<u>ROOT CAUSE OF EMISSIONS</u>
3-26-12	1	CO	0000	0359	Thick bed, draft issues due to Pluggage
<u>Explanation and plant status (Describe bed thickness, plant status (S/U, S/D?) OFA?UFA, fuel state, SNCR/SDA/Baghouse status etc):</u> Bed thick and starting to overfeed, bed has started to fuse together and prevent UGA from penetrating bed					
<u>Corrective Action taken:</u> Dropped load to 180K, south burner in service, increased grate speed to 100%, increased UGA ,feeding from different area of pit.					

SHIFT SUPERVISOR NAME: Wilson  
CONTROL ROOM OPERATOR: Coley

3-25-12

18:00-0600

00 Dil R, Josh B, Louis M,  
Judy S, David R, Willie C  
B. Coley

Judy Feedin all Boile

00 B101 load is 210K  
B102 load is 240K  
B103 load is 180K

00 #1 TB 53mw #2 TB 20mw

00 all Boile are Herin CO

00 B101 Feedin are in Emergency.

00 B103 Burner are in service due  
to 96 steam and CO spike.

00 All Boile #2 TB are in Manual.

00 B101 FF Comp outlet pressure is 96'  
18.5 in

00 All Boile ERV are in Manual.

00 the Feed quality is poor.

00 B101, B103 are on steam flow  
Mode

00 B101, B103 Making adjustments  
to control CO.

MAR 25 2012

- 18:00 B101, B102 are having some opacity
- 18:00 B102 77 comp outlet pressure is 96.18
- 18:00 All Drum They are in service
- 19:42 Clean the lime slurry tank strainer
- 19:47 Sulfuric line at the lab tank has a 96ale w/o in.
- 19:50 B101, B102 Riddling are Exercises
- 20:04 V-5 has a Broken Bolt
- 20:04 B103 96: steam flow spike and CO.
- 20:05 B102 opacity is spiking on 2-8 7-7 comp.
- 20:10 B101 opacity is 96: 2.09 Checkin 7-7 comp
- 20:40 B101 and B103 CO is swing
- 20:40 B103 increasing the load to 200
- 20:50 B103 run #4 gone #5 is plug Cleared.
- 20:54 P112 Motor is Bad
- 21:00 B101 popping doors due to 96 outlet pressure.

V-5 1400 Energy and C-4  
V-8. Main on

17 B102 76. Co due to steam flow  
spike up, belusted the 07-6  
anel pressure.

18 B101 load is at 230K  
B103 load is at 215K

19 B102 spot Blower is warmin  
Econo Temp 552  $\Rightarrow$  520

20 B103 spot Blower is warmin  
Econo Temp 475  $\Rightarrow$  459

21 stop the gallery Belt due  
to V-5, V-8 are back up.

22 B102 77-comp 2-8 is so  
due to 76: opacite.

23 B103 77 comp Checking the  
Shake doing a Cleaning Cycle

MAR 26 2012

24 B103 Burner is out.

25 B101 76: Co spike, load is at 235K  
B102 load is at 240K  
B103 load at 235K

B101 spot Blower is warmin  
Econo Temp 536  $\Rightarrow$  522

26 B101 #3 gate is in blam.

27 B101 load lower to 200K

- 01:40 B101 load at 200K due to thick Beel
- 01:40 B101 slug with wet fuel
- 01:47 B101 load lower to 180K due to steam spiking
- 01:42 B101 adjusted the OFA 100%
- 01:49 B101 put the Burner in serv
- 01:51 B101 North Burner Trip on Flame Failure.
- 02:00 B101 fuel is wet, slug load dropping out.
- 02:00 B101 outlet pressure is 96i
- 02:00 B101 load is at 150K due wet fuel.
- 02:08 B101 Burner are in service
- 02:08 B101 lower the OFA to 30%
- 02:08 B101 pressure is at 17 in.
- 02:20 B101 stop Blower part due to 96i steam and CO spike
- 02:42 B103 Drop load to 225 d to steam flow spiking and C
- 02:57 stop the gallery Belt Fan
- 03:08 B101 south Burner Trip



Pinellas County Resource Recovery Facility  
Pinellas County, Florida

Exceedance report for the period from Monday, March 26, 2012 to Monday, March 26, 2012

Device: IN\_MCS\_S1

Component: B1 O2 Corr CO (ppm)

Report Summary for 4-hour interval

Exceedance	Duration (D:H:M)	Reason
100.00%	00:04:00	Exceedance Condition
100.00%	00:04:00	Operating hours in the reporting period = 4 hours

Report Details for 4-hour interval

Start Time	End Time	Duration Average	Reason Action
03/26/2012 00:00	03/26/2012 04:00	00:04:00	Exceedance Condition
		100	Exceedance Condition Resolved
Total Duration:		00:04:00	Total number of Events: 1