

TAMPA ELECTRIC

July 1, 2002

Mr. Clair Fancy Chief Bureau of Air Regulation Florida Department of Environmental Protection 111 South Magnolia Drive, Suite 4 Tallahassee, FL 32301

Re: Tampa Electric Company (TEC)
F.J. Gannon Station
Title V Permit No. 0570040-014-AV
Request for Generic Exemption
Slag Storage

Dear Mr. Fancy,

## RECEIVED

JUL 02 2002

BUREAU OF AIR REGULATION

Via Fed Ex Airbill No. 7904 7115 9050

This purpose of this correspondence is to notify the Florida Department of Environmental Protection (DEP) that Tampa Electric Company (TEC) intends to utilize the fuel yard at F. J. Gannon Station (Gannon Station) to temporarily store slag from another electric utility. This slag is used as a material, with glassine properties, for blasting activities.

TEC is submitting the request for a generic exemption to ensure that this is included in Gannon Station's Title V Permit. TEC believes that this qualifies as a generic exemption per the Florida Administrative Code (F.A.C.) 62-210.300(3). TEC believes that this request does not need to be formally submitted until permit renewal per F.A.C. 62-210-300(3). However, in the interest of completeness and open disclosure TEC is informing the DEP with this letter.

The slag will be brought in by barge at infrequent intervals and stored in the fuel yard until needed by Reed Minerals. When the slag is needed, Reed Minerals will bring trucks into the storage area, load the slag and remove it from the site. This activity will occur on an infrequent basis, and it is estimated that the maximum amount of slag handled at the fuel storage area would be no more than 20,000 tons per year. Based on its glassine properties, the slag has minimal dust potential.

Attached is a block diagram with the illustrated transfer points. The slag is loaded into the hopper on the dock with the clamshell and is transferred onto the B conveyor. It is then transferred from the B conveyor to the C conveyor. From the C conveyor it moves to the D-2 conveyor through the T1structure (transfer structure 1). Finally, it is transferred from the D-2 conveyor to the E2 conveyor through the T2 structure (transfer structure 2). The E2 conveyor stacks the slag material in the North Yard. Once in the North Yard, the slag is the responsibility of Reed minerals. The trucking firm hired by Reed Minerals will load and haul the slag away.

TAMPA ELECTRIC COMPANY P. O. BOX 111 TAMPA, FL 33601-0111

(813) 228-4111

Mr. Clair Fancy July 1, 2002 Page 2 of 2

TEC currently has an agreement with Reed Minerals to accept 20,000 tons, annually. TEC has agreed to accept the slag in approximately 5,000-ton allotments per shipment. Currently, TEC has received approximately 5,00 tons of the slag.

Given the properties of the slag and the expected amounts to be handled on-site, the slag handling activity will fall well below the 5.0 tons per year threshold for fugitive emissions of particulate matter. The slag will not emit lead or any hazardous air pollutants. There is no unit-specific requirement for slag handling, and the additional emissions from the activity will not cause the facility to exceed any major source thresholds, even in combination with emissions from all other insignificant emission sources. Therefore, the slag handling activity will quality for a generic exemption and constitute as an "insignificant activity."

Based on this information, TEC believes that this operation is exempt from permitting per F.A.C. 62-210.300(3) and requests written concurrence from the Department. TEC appreciates the Department's immediate consideration in this matter.

If you have any questions, please feel free to telephone Shelly Castro or me at (813) 641-5033.

Sincerely,

Laura R. Crouch

Manager - Air Programs
Environmental Affairs

EA/bmr/SSC125

Enclosures

c/enc: Mr. Jerry Kissel, FDEP SW

Mr. Scott Sheplak, FDEP Ms. Alice Harman, EPCHC


# Attachment A Responsible Official Certification

## **Responsible Official Certification**

I have reviewed this letter of request for a generic permit exemption to transport and store slag at F.J. Gannon Station. I hereby certify that these documents are authentic and accurate to the best of my knowledge.

Date: 6/28/02

Signature: Karen Steffield
General Manager F.J. Gannon Station





#### MATERIAL SAFETY DATA SHEET

(Complies with 29 CFR 1910.1200)

#### SECTION I-GENERAL

Reed Minerals, Harsco Corporation

P.O. Box 0516

Camp Hill, PA 17001-0515

Emergency Telephone Number

(717) 763-4200

Product Name:

CAS Number:

RMS

14464-46-1 (Cristobalite)

14808-60-7 (Quartz)

Particles not otherwise regulated.

Common Namo: Slag, Coal

Date:

February, 1998

#### SECTION II - INGREDIENTS

Slag, Coal

100% - 89.0%

Cristoballte

0% - 0.3%

Quartz

0% - Q.2%

	OSHA PEL	ACGIH TLV
Total Particulate	15	. 10
Respirable Particulate	<b>5</b>	3
		•
Total Dust	(30 mg/m³ /% S(O <sub>2</sub> +2)	N/A
Respirable Dust:	(10 mg/m³ /% SIO <sub>2</sub> +2)	0.10
Total Dust:	(use 1/2 the value calculated from the count or mass formula for guartz)	N/A
Respirable Dust:	(use 1/2 the value calculated from the count or mass formula for quartz)	0.05
	Respirable Particulate Total Dust Respirable Dust: Total Dust:	Total Particulate Respirable Particulate  Total Dust Respirable Dust:  (30 mg/m³ /% SiO₂+2) Respirable Dust:  (10 mg/m³ /% SiO₂+2)  Total Dust:  (use 1/2 the value calculated from the count or mass formula for quartz)  Respirable Dust:  (use 1/2 the value calculated from the count or mass formula

<sup>&</sup>quot;Values expressed as mg/m"

#### SECTION III - PHYSICAL DATA

Physical Form:

Solid (angular granules)

Boiling Temperature:

N/A

Melting Temperature:

Greater than 2300°F

Vapor Preceure/Danalty:

N/A

Evaporation Rate:

N/A

Specific Gravity:

2.7 g/cc (typical)

Water Solubility:

Negligible

Color

Dark Green/Black

Oder:

None

#### SECTION IV - FIRE AND EXPLOSION DATA

Product is nonflammable and nonexplosive.

#### **SECTION V - REACTIVITY DATA**

Product is stable under normal conditions of use, storage, and transportation.

#### SECTION VI - HEALTH HAZARD DATA

RMS aggregate may contain up to 0.3% cristobalite; one of the three major forms of sillcon dioxide (crystalline elica). Quartz may be present up to 0.2%, tridymite has not been detected. RMS aggregate, as shipped, do not pose a significant health hazard and should be treated as a nuisance dust. The only significant route of exposure which could pose some level of health hazard is inhalation of respirable particles which may occur during use. As shipped, there are essentially no respirable particles in RMS aggregate. Contact with intact skin is not known to cause health effects. Eye contact may cause irritation but has no known toxic effects.

The International Agency for Research on Cancer (IARC) reviewed the evidence for the carcinogenicity of crystalline silicas in animals. One study utilized intrapleural injection of cristobalite with particles in the respirable range. Malignant lymphomas of the histocytic type were observed in the treated rats.

Cristoballib and quartz are not identified as carcinogens by OSHA but are identified as probable carcinogens by the International Agency for Research on Cancer (IARC) and reasonably anticipated to be carcinogens by the United States Department of Health and Human Services' National Toxicology Program (NTP).

Respirable quartz tested for carcinogenicity in rate by chronic inhalation and in rate by single or repeated intratracheal instillation, produced a significant increase in the incidences of adenocarcinomas and squamous cell cercinomas of the lung. Based on this study and on those on other forms of crystalline slica, IARC considered the evidence for the carcinogenicity of crystalline silica in experimental animals to be sufficient.

In humans, overexposure to respirable crystalline silica is known to cause silicosis. Silicosis is a chronic disease characterized by the formation of scattered, rounded or stellate silica-containing nodules of scar tissue in the lungs, ranging in size from microscopic to 1.0 cm or more. This can cause symptoms of coughing, dyspnes, wheezing and nonspecific respiratory aliments. Some epidemiology studies have shown a potential connection with lung cancer in those professions with high exposures to respirable silica. Many other studies have falled to find such a connection; however, tobacco smoking and high dust exposure exhibited a synergistic relationship. Pre-existing lung conditions may aggrevate the results of exposure to silica dust.

(RM 2/88)

RECEIVED AUG 2 4 1992

#### LABORATORY REPORT

LAB NUMBER: 2418

August 20, 1992

CLIERT

Reed Minerals

SAMPLE HISTORY:

SAMPLED BY: DATE SAMPLED: 8-13-92 LOCATION: West Alton DATE RECEIVED: 8-14-92 DESCRIPTION: Raw Coal Slag DATE COMPLETED: 8-18-92

TESTS REQUIRED: FEDERAL TEST METHOD 1311 - Toxicity

Characteristic Leaching Procedure

SAMPLE LOCATION: Rail Car

HEBULTE:			ICP
ELEMENT TESTED	RESULTS	Marimum Allowable	DETECTION LIMITS
Arsenic	*BDL	5.0 ppm	0.02
Selenium	0.041 ppm	1.0 ppm	0.01
Chronium	*BDL	5.0 ppm	0.01
Cadmium	*BDL	1.0 ppm	0.003
Lead	*BDL	5.0 ppm	0.05
Barium	*BDL	100.0 ppm	0.002
Hercury	<b>±BDL</b>	0.2 ppm	**0.03
<b>Silver</b>	0.045 ppm	5.0 ppm	0.01

THIS NATERIAL IS NOT CONSIDERED TO BE A HAMARDOUS WASTE ACCORDING TO ROBA REGULATIONS FOR THE LEACHABILITY OF 8 HEAVY MORTALS,

\* Below Detectable Limits

\*\* The mercury lavel was below the detection limits of the ICP. Since the detection limits are well below the maximum allowable concentration and there is no reasons (per the submitting agency) to believe that mercury is a contaminant, it is reasonable to assume mercury is not at a level which will classify the product as a hazardous waste.

\*\*\*There are no EPA limits for copper and zinc, local regulations may apply.

TEST PERFORMED BY: Doning M. Doszema

TEST REVIEWED BY: Gary L. Tinklenberg

Chamiet

WRITTEN REPORT BY: B.A. Dockemb

## REED MINERALS

Maharsco company

#### MATERIAL SAFETY DATA SHEET

(Complies with \$8 CFR (916,1200)

### RECTION I. DEVERAL

Read Minantia, Haraca Corporation RO, Box 0515 Camp Hill, PA 17001-0515

Briggency, Tetaphone Number: (717) 729-4200

Product Name : Disch Beauty

Akreshes

68479-68-8 CAS Number

Particulates not

atherwise regulated.

Common Manue :

Bing, Coal April, 1997

<b>N</b> . 1.	,	WENCOIENTE
	6/ W	LANGE CHITE
32678		

Glag, Cost 189%

	ODIA PEL	acgh Tily
Millannoe Parliculata Yest Pertissiase	1 16	10
Respirable Particulate	ri Š	. 5

### ERCTION IN - PHYSICAL DATA

Photes Form
Moting Temperature
Meting Temperature

por Pramum Danaltr

Evaporation A Spackie Gravi

Miriur Balubilly Catar

Udar

Bolid (annular granulas)

NA

Greater than 2000 F

N/A

NA

27 pro: (typical) Negligibia

Black

None

## SECTION N. PIRE AND EXPLOSION DATA

Product is runfismmable and nonexplosive

Post-It Fax Note 7671	Date 4/25 Pages 2
TO GREG RILL	Frozi JAsan
Co/Dept.	Co.
Preno # 630-7/07	Phone #
FEN SAME 95 2 YES	FBX # AG-U

#### PACTION V- REACTIVITY DATA

Hinduct is state under normal conditions of use, storage, and transportation,

Post-k" brand tax transmidal memo 767   For pages > 2		
By seath	From Miko	
Sec. Company	ta	
Days.	Phone &	
Pest #	Fex F	
The second lives the se	<u></u>	

#### SECTION VI - HEALTH HAZARD DATA

Low health tiek by inhalesian. That as a nylennes sust. Typical tree what lean than 0.1%. This material is not a recognized cordinagen or coolidinagen. Human toxic response has not been demonstrated for any route of entry. Mechanical inhadon may contin to eyes, sidn, or respiratory tract. Precedeting health conditions may be aggrevated.

Depoins particity; NTP - No; LARC Monographs • No: OSHA Regulated - No.

## FIRST AUD IN CASE OR

- 1. Eye Contact brimadiately flush eyes thoroughly with water or an ophilistrate sating solution. 2. Alde Compet West skip with seep and water it mission occurs.
- 3: Inhalation Hemove affected person(e) to west air source.
- 42 Oral Intaka Pitase mouth our with weter.

dymptoms persial, contact a physiolen or other medical personnel.

#### SECTION VII - BRILL LEAKAND DISPOSAL PROCEDURES

No special procedures required for clean-up. Wetting with water will reduce airborns dust.
Upconteminated product does not exceed Taxicity Characteristic Loaching Procedure (TCLP) limits: and may be disposed of as an inart material in an appropriate solid waste landfil according to applicable Federal, Some and Lace requisitant.

#### SECTION VIII - CONTROL MEASURES

Lisa appropriate NICEN pertition map introduction when exposure limits may be exceeded. Mointain sufficient ventilistion to allow visual control with work surfaces. Apprepriate abrasive blastar's protective equipment is required, which may also include glowes, mod with protective lend optiony places, and hearing protection.

#### SECTION IX - SPECIAL PRECAUTIONS

Keep product dry and free of all contendnation to easure tree flow. Use an appropriate entury screen gvor fill heach of begging por. Respirable dust may be generated during pressure abrusive cleaning DA OFFECTIONE

#### - NOTE-

The opinions expressed herein are those of qualified expens within Herete Corporation. Haraco bigliower that are information combined herein is current and accurate for the normal shid inherded ulso of this product an of the data of the Material Safety Data Sheet. Since the use of this information and of those opinions or the conditions of use of the product are not within the portrol of these co Corporation, it is the user's obligation in detaining and observe the conditions of sets use and disposal of the product by their operators.

(R)4 4/87)