

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: MFM Industries	ID #: 0830017
Inspection Date: 11/9/09	Sky Conditions: partly cloudy
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Michael S. Gascoigne (MFM Industries)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2009-2010\Wanda's Inspections\Lake\MFM Industries\Photos	



Photo 1: A dust cloud located in the middle of the facility which was observed upon entering the facility.



Photo 2: A dust cloud located in the middle of the facility which was observed upon entering the facility.



Photo 3: Approximately 10 ft vertical sprinklers in the background along the front end of parking area.



Photo 4: Tank #9 containing only dust from the collection system is located in the background.

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: MFM Industries	ID #: 0830017
Inspection Date: 11/9/09	Sky Conditions: partly cloudy
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Michael S. Gascoigne (MFM Industries)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2009-2010\Wanda's Inspections\Lake\MFM Industries\Photos	



Photo 5: Tanks #7 and #8 containing product.




Photo 6: Tanks #1, #2, #3, #4 and #5 - four containing product and one containing bentonite.



Photo 7: Front view of the load out area.



Photo 8: Close up view of the discharge shuttes inside the load out area.

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: MFM Industries	ID #: 0830017
Inspection Date: 11/9/09	Sky Conditions: partly cloudy
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Michael S. Gascoigne (MFM Industries)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2009-2010\Wanda's Inspections\Lake\MFM Industries\Photos	




Photo 9: Side view of the load out area showing accumulation of unconfined particulate matter.



Photo 10: Side and frontal view of load out area showing inoperable sprinkler system.



Photo 11: Accumulated clay-like material on the side of Mr. Roland's (complainant) vehicle.



Photo 12: Accumulated clay-like material on the windshield/hood of Mr. Roland's vehicle.

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: MFM Industries	ID #: 0830017
Inspection Date: 11/9/09	Sky Conditions: partly cloudy
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Michael S. Gascoigne (MFM Industries)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2009-2010\Wanda's Inspections\Lake\MFM Industries\Photos	



Photo 13: Accumulated clay-like substance on the top of Mr. Roland's vehicle.



Photo 14: Accumulated clay-like substance on the windshield/hood of a neighbor's vehicle.



Photo 15: Accumulated clay-like substance covering the barbeque grill and chair on the enclosed porch David & Lilia Kiefer (Mr. Roland's tenants who live next door).



Photo 16: Accumulated clay-like substance covering the barbeque grill and chair on the enclosed porch of David & Lilia Kiefer.

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: MFM Industries	ID #: 0830017
Inspection Date: 11/9/09	Sky Conditions: partly cloudy
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Michael S. Gascoigne (MFM Industries)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2009-2010\Wanda's Inspections\Lake\MFM Industries\Photos	



Photo 17: Accumulated clay-like substance covering the outside air conditioning unit of David & Lilia Kiefer.



Photo 18: Accumulated clay-like substance covering the vegetation located directly across the road (CR 329) from MFM Industries.



Photo 19: Accumulated clay-like substance covering the vegetation located directly across the road (CR 329) from MFM Industries.