

Florida Department of Environmental Protection Inspection Photo Log

Facility Name: Anderson Columbia Plant #8	ID #: 0830135
Inspection Date: 11/3/11	Sky Conditions: Clear
Persons Present: Wanda Parker-Garvin (FDEP, photographer), Stewart Carroll (Asphalt Operations Manager)	
Digital camera used. Photo files saved at: O:\COMPLIANCE-Central Files\Inspection Reports 2011-2012\Wanda's Inspections\Marion\Anderson Columbia 0830135	



Crusher unit and engine located to the right.



Screener and four (4) conveyor belts.



Side of unit with 5th conveyor belt.



Engine for the screener.



Loader for the crusher with initial screener.



The asphalt plant.