DIGITAL PHOTOGRAPHIC LOG

- 1. Facility Name: Standard Carbon
- 2. County / Facility ID No: Marion / 0830170
- 3. Inspection Type: INS24. Inspection Date: 07/12/11
- 5. Type of Camera Used: Canon Power Shot 5.0 mega pixels A530 (Air Section digital camera)
- 6. Digital Recording Media: Canon 16 MB MultiMediaCard
- 7. All Digital Photos Were Copied To: N/A
- 8. Original Copy Is Stored On: Nedin Bahtic's Computer\Documents and Settings\Bahtic_N\My Documents\My Pictures\Inspections\Marion\0830170 Standard Carbon (07-12-11)
- 9. Were the photos altered?: NO YES explain yes:
- 10. Photographer: Nedin Bahtic
- 11. Signature of Photographer:_____



Photo ID No. / Date / Time: IMG_1328 / 07-12-11 / 1020 Mahle and Flex-Kleen baghouses

Facility Name: Standard Carbon

Facility ID No: 0830170

Inspection Date: 07/12/11

Page 1 of 17



Photo ID No. / Date / Time: IMG_1329 / 07-12-11 / 1020 Truck unloading building; Silos 9 & 11

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 2 of 17



Photo ID No. / Date / Time: IMG_1330 / 07-12-11 / 1020 Standard Carbon facility – view from west

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 3 of 17



 $Photo\ ID\ No.\ /\ Date\ /\ Time:\ IMG_1331\ /\ 07\text{-}12\text{-}11\ /\ 1020\\ \textbf{Standard\ Carbon\ facility-view\ from\ west}$

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 4 of 17



Photo ID No. / Date / Time: IMG_1332 / 07-12-11 / 1031 Wet fly ash receiving area

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 5 of 17



 $Photo\ ID\ No.\ /\ Date\ /\ Time:\ IMG_1333\ /\ 07\text{-}12\text{-}11\ /\ 1034\\ \textbf{Standard\ Carbon\ facility-view\ from\ north}$

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 6 of 17



Photo ID No. / Date / Time: IMG_1334 / 07-12-11 / 1037 Flex-Kleen and Mahle baghouses

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 7 of 17



Photo ID No. / Date / Time: IMG_1335 / 07-12-11 / 1039 Carbon storage silos

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 8 of 17



Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 9 of 17



Photo ID No. / Date / Time: IMG_1337 / 07-12-11 / 1046 Exhausts from Kilns 2 & 1

Facility Name: Standard Carbon Facility ID No: 0830170

Inspection Date: 07/12/11 Page 10 of 17



Photo ID No. / Date / Time: IMG_1338 / 07-12-11 / 1050 Exhausts from Kilns 1 & 2

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 11 of 17



Photo ID No. / Date / Time: IMG_1339 / 07-12-11 / 1050 $\bf Mikro\ Pulsaire\ and\ PJ-3\ baghouses$

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 12 of 17



Photo ID No. / Date / Time: IMG_1341 / 07-12-11 / 1059 ${\bf PJ-2\ baghouse}$

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 13 of 17



Photo ID No. / Date / Time: IMG_1342 / 07-12-11 / 1109 Exhausts from Kilns 2 & 1

Facility Name: Standard Carbon Facility ID No: 0830170

Inspection Date: 07/12/11 Page 14 of 17



Photo ID No. / Date / Time: IMG_1344 / 07-12-11 / 1134 ${\bf PJ\text{--}T}$ baghouse

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 15 of 17



Photo ID No. / Date / Time: IMG_1345 / 07-12-11 / 1134 $\,$ Blower for PJ-T baghouse

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 16 of 17



Photo ID No. / Date / Time: IMG_1346 / 07-12-11 / 1134 $\bf PJ-1$ baghouse

Facility Name: Standard Carbon
Facility ID No: 0830170

Inspection Date: 07/12/11
Page 17 of 17