

EPA VISIBLE EMISSION OBSERVATION FORM 1

Method Used (Circle One)
Method 9 203A 203B Other: _____

Company Name
EPOL SAWMILL

Facility Name

Street Address

City _____ State _____ Zip _____

Process
COMBUSTION TURBINE Unit # **B** Operating Mode
FULL LOAD

Control Equipment _____ Operating Mode _____

Describe Emission Point
STACK

Height of Emiss. Pt.		Height of Emiss. Pt. Rel. to Observer	
Start 80 End 80	Start 80 End 80		
Distance to Emiss. Pt.		Direction to Emiss. Pt. (Degrees)	
Start 1200 End 1200	Start 60 End 60		

Vertical Angle to Obs. Pt.		Direction to Obs. Pt. (Degrees)	
Start 28 End 20	Start 60 End 60		
Distance and Direction to Observation Point from Emission Point			
Start 1210 End 1210	Direction UP		

Describe Emissions

Start **NONE** End **NONE**

Emission Color _____ Water Droplet Plume _____

Attached Detached None

Describe Plume Background

Start **SKY** End **SKY**

Background Color _____ Sky Conditions _____


Start **WHITE** End **WHITE** Start **PC** End **PC**

Wind Speed _____ Wind Direction _____

Start **3-5** End **3-5** Start **SW** End **SW**

Ambient Temp _____ Wet Bulb Temp _____

Start **80°** End **80°** RH Percent _____



Additional Information

Form Number _____ Page _____ of _____

Continued on VEO Form Number _____

Observation Date		Time Zone				Start Time	End Time
2-20-03						3:02	
Min	Sec	0	15	30	45	Comments	
	02	0	0	0	0		
03	0	0	0	0			
04	0	0	0	0			
05	0	0	0	0			
06	0	0	0	0			
07	0	0	0	0			
08	0	0	0	0			
09	0	0	0	0			
10	0	0	0	0			
11	0	0	0	0			
12	0	0	0	0			
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Observer's Name (Print)
GARY KUBERSKI

Observer's Signature
Gary Kuberski Date **20-FEB-03**

Organization
FDEP

Certified By
ETA Date **14-FEB-03**