

DIGITAL PHOTOGRAPHIC LOG

1. **Facility Name:** Cemex concrete batch plant, Eaton Park, Lakeland, FL
2. **County / AIRS ID No:** Polk County / 1050073
3. **Inspection Type:** INS2: Walkthrough inspection and visible emissions (VE) test audit.
4. **Inspection Date:** 05/02/2012
5. **Date Photographic Log was completed:** 05/10/2012
6. **Camera Used:** Samsung MetroPCS mobile phone camera, phone type is R380.03.
7. **Recording Media:** Phone Memory, Samsung MetroPCS mobile phone camera, phone type is R380.03.
8. **All Digital Photos Were Copied To:** Hard Disk of Computer and to this photo log.
9. **Original Copy Is Stored In/On:** Hard disk of computer.
10. **Were the photos altered?:** NO YES explain yes:
11. **Photographer:** Amaury Betancourt
12. **Signature of Photographer:** _____ N/A _____



Photo ID No: 1050073_Photo_05_02_2012-001

Time: 05/02/2012, Approx. 09:00 AM

View of conveyor belt and open channel, which is filled with dark and filmy water. Open channel is on the property of Cemex, but has never been used by Cemex since it was left by the previous property owner's facility. Camera is facing Approx. West.

Facility Name: Cemex (Eaton Park, Lakeland, FL)

Facility ID No: 1050073

County: Polk

Inspection Type/Date: INS2: Facility Walkthrough and Visible Emissions (VE) Test Audit

Page 1 of 2



Photo ID No: 1050073_Photo_05_02_2012-002

Time: 05/02/2012, Approx. 09:00 AM

View of conveyor belt and open channel, which is filled with dark and filmy water. Camera is facing Approx. Northwest.

####