DIGITAL PHOTOGRAPHIC LOG

- 1. Facility Name: Cemex Four Corners (Davenport) Ready Mix and Block Plant
- 2. County / AIRS ID No: 1050350
- 3. Inspection Type: INS3: Inspection and VE Test Audit
- 4. Inspection Date: 01/24/2012
- 5. Photo log completed: 02/09/2012
- 6. Type of Camera Used: Olympus Camedia Digital Camera, 5.0 Megapixel, C-50 ZOOM, S/N 115248297
- 7. Digital Recording Media: FUJIFILM xD-Picture Card, 128 MB, S/N DPC-128, R31695 5RZ7, 0244 MAD
- 8. All Digital Photos Were Copied To: Hard drive of desktop computer DEP 143271. Some photos are on this Digital Photographic Log, but many photos are redundant so have been left out of photo log.
- 9. Original Copy Is Stored In/On: Hard drive of desktop computer DEP 143271.
- 10. Were the photos altered?: NO_X_ YES____ explain yes:
- 11. Photographer: Amaury Betancourt
- 12. Signature of Photographer:_



Photo ID No: 1050350_Photo_01_24_2012-1

Time: Approx. 13:40 PM

The North silo (front silo in photo) is EU006, also listed as silo #2, and was filled with white cement. The South silo (back silo in photo) is EU005, also listed as silo #1, and was filled with grey cement. Camera facing approx. S.




Photo ID No: 1050350_Photo_01_24_2012-3

Time: Approx. 13:40 PM

View of North silo (EU006) with South silo (EU005)

behind. Camera facing approx. S.

Facility Name: Cemex Four Corners (Davenport) Ready Mix and Block Plant

Facility ID No: 1050350 County: Polk Inspection Type/Date: INS3 / 01-24-2012 Page 1 of 4



Photo ID No: 1050350_Photo_01_24_2012-15

Time: Approx 14:25 PM

View of both the North silo (EU006) and the South silo

(EU005), camera facing approx. W.



Photo ID No: 1050350_Photo_01_24_2012-16

Time: Approx 14:25 PM

View of truck loading grey cement into South silo (EU005), camera facing approx. W. The white cement truck is behind the grey cement truck in the photograph.



Photo ID No: 1050350_Photo_01_24_2012-17

Time: Approx 14:25 PM

North silo is in background of photo, camera facing approx. W. Grey cement truck is in foreground of photo and white cement truck is visible behind grey cement

truck.



Photo ID No: 1050350_Photo_01_24_2012-18

Time: Approx 14:25 PM

Grey cement truck is in foreground of photo and white cement truck is visible behind grey cement truck; camera

facing approx. NW.

Facility Name: Cemex Four Corners (Davenport) Ready Mix and Block Plant

Facility ID No: 1050350 County: Polk Inspection Type/Date: INS3 / 01-24-2012 Page 2 of 4




Photo ID No: 1050350_Photo_01_24_2012-7

Time: Approx 14:00 PM

Approximate view from where VE tests were conducted for EU005 and EU006; camera facing approx. NE.



Photo ID No: 1050350_Photo_01_24_2012-8

Time: Approx 14:00 PM

View of silos from approximate perspective of where VE tests were conducted for EU005 and EU006; camera

facing approx. ENE.



Photo ID No: 1050350_Photo_01_24_2012-6

Time: Approx 13:50 PM

Some of the manufactured products stored at the facility,

North side of the facility; camera facing approx. N.



Photo ID No: 1050350_Photo_01_24_2012-12

Time: Approx 14:20 PM

Weighing and batching operations located inside the building at the facility; camera facing approx. NE. Silos are outside the building, just behind this equipment.

Facility Name: Cemex Four Corners (Davenport) Ready Mix and Block Plant

Facility ID No: 1050350 County: Polk Inspection Type/Date: INS3 / 01-24-2012 Page 3 of 4



Photo ID No: 1050350_Photo_01_24_2012-11

Time: Approx 14:20 PM

Some weighing and batching equipment located inside the building at the facility; camera facing approx. ENE.



Photo ID No: 1050350_Photo_01_24_2012-14

Time: Approx 14:20 PM

Top of the conveyor belt that is part of the weighing and batching equipment inside the building at the facility;

camera facing approx. NW.




Photo ID No: 1050350_Photo_01_24_2012-13

Time: Approx 14:20 PM

Conveyor belt that is part of the weighing and batching equipment inside the building at the facility; camera

facing approx. N.



Photo ID No: 1050350_Photo_01_24_2012-4

Time: Approx 15:50 PM

Some of the manufactured products at the facility; camera

facing approx. N.

Facility Name: Cemex Four Corners (Davenport) Ready Mix and Block Plant

Facility ID No: 1050350 County: Polk Inspection Type/Date: INS3 / 01-24-2012 Page 4 of 4