

HUMAN CREMATORY



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE :	ANNUAL (INS1, INS2)	COMPLAINT/DISCO	VERY (CI)		
	RE-INSPECTION (FUI)	ARMS COMPLAINT	NO:		
AIRS ID#: 0810200 DA	TE: <u>12/14/2009</u>	ARRIVE: 1:04pm	DEPART: 4:15p	<u>m</u>	
FACILITY NAME: BR	ROWN & SONS FUNERAL HO	OMES			
FACILITY LOCATION	N: 604 43rd Street West				
	BRADENTON 3420	9-3908			
OWNER/AUTHORIZE	CD REPRESENTATIVE: DA	ALE BROWN PHO	ONE: (941)758-7788		
CONTACT NAME:		РНО	ONE:		
ENTITLEMENT PERIO	OD: 1/1/2007 / 1/1/2012 (effective date) (end date)				
☐ IN COMPLIAN	CE MINOR Non-COM	MPLIANCE SIGNIFIC	CANT Non-COMPLIANCE	3	
PART II: TESTING/RE	ECORDKEEPING REQUIRE	EMENTS – Rule 62-296.401	. F.A.C.		
(check ☑ appropriate			,		
	ojectionable odor(s) detected? ssions test conducted during thi			☐ Yes ⊠ No	
62-297, F.A.C.)?-	estrate individual source compli			⊠Yes ☐ No	
days prior to the A	AGP Notification form submiss (5)(i), F.A.C.)	ion, and within 60 days prior	to each anniversary date?	□Yes □ No	
4. In order to demon	strate individual source complia	ance were the remaining appl	icable standards testing		
completed within 60 days prior to the AGP Notification form submission? (Rule 62-210.300(4), F.A.C.) Yes No a) Carbon Monoxide (CO) emissions equal to or below the requirements of 100 parts per million by					
10 (Ref.: Chapter	s, corrected to 7% O_2 on an hour 62-297, F.A.C.)?				
	erformed according to EPA Me tter emissions test with results of	-		☐Yes ☐ No	
	c foot (ft ³)of flue gas, corrected -297, F.A.C.)?	to 7% O. and tested according		□Yes □ No	
	s testing conducted with the sou				
6. Was CO & PM co				⊠Yes □ No	
	ompliance demonstrated by sub-	rce operating at the manufact	urers recommendedidentical crematory unit?	☐Yes ☐ No	
7. Was the Departme8. Was the required to	ompliance demonstrated by sub- ent notified at least 15 days pric test report filed with the Depart oleted?	rce operating at the manufact mission of a test report for an or to the date of the last formation as soon as practical, but	urers recommended identical crematory unit? compliance test? to longer than 45 days after	☐Yes ☐ No ☑Yes ☐ No	

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-296.401, F.A.C. (check ☑ appropriate box(es))	
1. Is there Continuous Emissions Monitoring System (CEMS) equipment installed on each unit to record	temperatures in the
primary and secondary chambers where there is a 1.0 second gas residence time in the secondary chamber co	ombustion zone in
accordance with the manufacturer's instructions?	
a) Do temperature probes seem to be properly placed?	
b) Are the following records kept on file, available for inspection for at least two years following the re-	
measurements, maintenance, reports and records?	cording of such
1) All measurements (including CEMS)	⊠vas □ Na
2) Monitoring device	⊠Yes ☐ No
3) Performance Testing Measurements	
4) CEMS Performance Evaluation	
5) All CEMS or monitoring device calibration checks	
6) Adjustments	Yes ∐ No
7) Preventive maintenance performed on systems/devices	
8) Corrective maintenance performed on systems/devices	⊠Yes ☐ No
2. Was this crematory unit constructed: (check only one ☑ box)	
a) BEFORE August 30, 1989? (If this box checked, continue on to #3 and skip #4)	
b) ON or AFTER August 30, 1989? (If this box checked, skip #3 and continue on to #4)	
3. If constructed BEFORE August 30, 1989 is the:	
a) secondary chamber combustion zone providing at least a 1.0 second gas residence time @ 1600°F ?	☐Yes ☐ No
b) actual operating temperature of the secondary chamber combustion zone no less than 1400°F	
throughout the combustion process in the primary chamber?	☐Yes ☐ No
c) cremation in the primary chamber begun after the secondary chamber combustion zone temperature	
is equal to or greater than 1400°F ?	☐Yes ☐ No
d) required monitoring equipment installed and operational, and providing continuous monitoring to	
record the temperature at the point or beyond where 1.0 second gas residence time is obtained in the	
secondary chamber combustion zone according to the manufacturer's instructions?	☐Yes ☐ No
4. If constructed ON or AFTER August 30, 1989 is the:	
a) volume in the secondary combustion zone sufficient to provide at least a 1.0 second gas residence time	ne
@ 1800° F?	⊠Yes □ No
b) the actual operating temperature of the secondary chamber combustion zone no less than 1600°F	
throughout the combustion process in the primary chamber?	⊠Yes ☐ No
c) secondary chamber combustion zone temperature equal to or greater than 1600°F before the crematic	
process begins in the primary chamber?	Yes ☐ No
5. Are appropriate cremation containers containing no more than 0.5 % (percent) by weight chlorinated	△105 → 110
plastics used during the cremation of dead human bodies?	⊠Yes □ No
a) If the answer to question 4 above is YES, is certifying documentation from the manufacturer that the	
are composed of 0.5% or less by weight chlorinated plastics kept on file at the site for the duration of	y F
their use and for at least two years after their use?	☐Yes ☐ No
b) Are there any other materials, including biomedical wastes (Rule 62-210.200, FAC) incinerated at this location?	DVac D Na
	∐Yes ⊠ No
6. Have all crematory operators been trained and certified by a Department-approved training program?	☐Yes ☐ No
a) Are copies of the training certificates for all crematory operators kept on file at the facility for the du	
of the operator's employment & for an additional two years after termination of employment?	☐Yes ☐ No

PART IV: SPECIAL CONDITIONS AND PROCEDUL A. New or Modified Process Equipment	RES – Rule 62-296.401, F.A.C.			
1. Since the last inspection has there beena) installation of any new process equipment?b) alterations to existing process equipment with	⊠No ⊠No			
 c) replacement of existing equipment substantially different than that noted on the most recent notification form?				
local program office?				
2. If a crematory unit has been modified to the extent that a Department air construction permit was required, have all operators been retrained to operate the modified unit? Yes No				
 In the case of new or modified equipment, where required, has the owner submitted copies of all op a) submitted within the 15 day required window 	perator training certificates? Yes	□No □No		
Wendy D. Simmons	12/30/2009			
Inspector's Name (Please Print)	Date of Inspection	_		
	12/30/2011			
Inspector's Signature	Approximate Date of Next Inspection	_		

COMMENTS: Pre-Inspection Review: Last inspection was conducted on 06/14/2007. According to inspection report, a FWN was issued for lack of MSDS sheets. MSDS sheets were later provided to the Department via fax. According to ARM's the last Visible Emissions testing was conducted on 11/12/2008 and testing was IN compliance. Visible Emissions testing scheduled for 1:00pm. Inspection Findings: This facility does not match times on the chart records with actual time of cremation, but they do enter start time on chart records at of beginning each cremation. Testing temperature was about 1600 F according to chart recording provided with testing. Found several cremations with missing "S", but start times were indicated by writing actual time on charts. Copies of repair and prevenative maintenance records were provided upon request. MSDS sheets were not available because facility only uses cardboard or wood for cremations, according to Mr. R. Brown. Copies of reports for testing conducted on this day were provided to the Department via mail from Southern Environmental on 12/16/2009. I reviewed records from 01/2008 through 12/11/2009. Chart recordings after 12/11/2009 were still in recorder. Took measurements for thermocouple location and witnessed Visible Emissions Testing conducted by Mr. Dale Wingler. The facility did have three cremations that dipped below 1600° F, these non-compliant issues were not reported to the Department as required in the facility entitlement. Copies of chart records were provided upon request for these three cremations (dates are 12/02/2009; 11/27/2009; and 12/09/2009). I reviewed Human Crematory Entitlement requirements and pointed out each requirement, as necessary. All charts that had low temperatures had indications of power failures/outages, but these non-compliant issues were also not reported to the Department as required in the facility entitlement.