

DIGITAL PHOTOGRAPHIC LOG

1. Facility Name: Hernando County Animal
2. County / AIRS ID No: 0530365
3. Inspection Type: INS 2
4. Inspection Date: 09/28/2012
5. Date Photographic Log was completed: 10/16/2012
6. Type of Camera Used: Canon Power Shot SD400 Digital ELPH
7. Digital Recording Media: ScanDisk 256 MB SD Card
8. All Digital Photos Were Copied To: Hard Disk of Computer 143986 and to Digital Photographic Log
9. Original Copy Is Stored In/On: Hard disk of computer 143986
10. Were the photos altered?: NO ___ YES XXX explain yes: photo sizes were reduced to fit in this log.
11. Photographer: Wendy D. Akins
12. Signature of Photographer: _____



Photo ID No: IMG_435 - photo shows front view of cremation unit. The unit is a Crawford C700P cremation unit.



Photo ID No: IMG_436 – Primary Chamber thermocouple located on left side of cremation unit.



Photo ID No: IMG_437 – View of chart record in place. Cremation unit warming up. This unit is capable of burning 350lbs. per hour.

DIGITAL PHOTOGRAPHIC LOG



Photo ID No: IMG_438 – Photo shows secondary chamber thermocouple placement on the right side of the cremation unit.



Photo ID No: IMG_442 – This photo shows view from the VE observation point. The cremation unit was in operation when this photo was taken.



Photo ID No: IMG_439 – This facility does use bag containers during cremation. This photo was taken as the unit was being loaded for the Visible Emissions Testing.



Photo ID No: IMG_441 – This photo shows the flame view port on the back of the cremation unit.