

Air Pollution Source Inspection Report Form

Florida Department of Environmental Protection, Southwest District

PAGE 1 OF 1**FACILITY: Bartow Manufacturing Plant - Metromont****ID#: 1050430****COUNTY: Polk****ADDRESS: 4151 US17, Bartow, FL 33830****INSPECTION DATE: 1-26-12****TIME IN: 10:30AM****TIME OUT: 10:45****CONTACT: Mr. Mark Felton****INSPECTION TYPE: INS1****EU(s) INSPECTED: Parking Lot****SOURCE DESCRIPTION: Concrete batching and manufacturing****CURRENT PERMIT: 1050430-001-AG****PERMIT EXPIRATION DATE: 06-04-14****INSPECTION FINDINGS**

I (Chris Haines) arrived at the facility after viewing quite a bit of dust blowing onto route US 17 South. Upon arrival I took a few pictures in the parking lot and then proceeded to the front office to speak with Mr. Mark Felton. I alerted him to the issue, and he was already aware, the facility was loading a water truck already. I advised him to alert Ms. Danielle Henry and see to it that the water truck is used as needed. I gave Mr. Felton Ms. Henry's email address and left the facility at approximately 10:45.

COMPLIANCE STATUS: IN / MNC / SNC**INSPECTOR'S SIGNATURE:****INSPECTOR'S NAME:**

Chris Haines

DATE:

1-27-11

Photographic Inspection Log

- **Facility Name:** Metromont, Bartow Facility
- **County / Facility ID No:** Polk/ 1050430
- **Inspection Type:** Drive-By, INS1
- **Inspection Date:** 01-26-12
- **Type of Camera Used:** Canon Power Shot 5.0 mega pixels A530 – Air Section digital camera
- **Digital Recording Media:** Canon 16 MB MultiMediaCard
- **All Digital Photos Were Copied To:**
- **Original Copy Is Stored In/On:** C:\Documents and Settings\haines_c\My Documents
- **Were the photos altered?:** NO X YES _____ **explain yes:**
- **Photographer:** Chris Haines



Picture ID No. 001
Southward Photo of parking lot during wind.



Picture ID No. 002
Westward photo of parking lot during wind.



Picture ID No. 003
South-west photo of parking lot after wind.