HARDEE POWER PARTNERS LIMITED

Invenergy

Via Federal Express

February 25, 2013

RECEIVED

FEB 27 2013

DIVISION OF AIR RESOURCE MANAGEMENT

Mr. Erin DiBacco Florida Department of Environmental Protection Southwest District Office 13051 North Telecom Parkway Temple Terrace, FL 33637-0926

Re: Hardee Power Partners Limited

Hardee Power Station

Title V Air Operation Permit No. 0490015-016-AV

July - December 2012 Monitoring Report

Dear Mr. DiBacco:

Pursuant to the requirements of conditions RR1 and RR4 of Appendix RR, and Condition 15 of Appendix CAM, Hardee Power Partners Limited (HPPL) hereby submits the attached semi-annual monitoring report for the Hardee Power Station for the July - December 2012 monitoring period.

Contact Matt Drennan at (863) 375-3266 ext. 227 if you have any questions regarding this information.

I certify that, based on the information and belief formed after reasonable inquiry, the statements and information in the documents are true, accurate, and complete.

Sincerely,

Tim Frost

Plant Manager

Enclosure

Cc: Florida Department of Environmental Protection
Division of Air Resource Management
Bureau of Air Regulation
Title V Section
2600 Blair Stone Road, Mail Station # 5505
Tallahassee, Florida 32399-2400

HARDEE POWER PARTNERS LIMITED

Invenergy

Excursions (as defined in Table 1 of Appendix CAM) for the July - December 2012 reporting period:

- CT1A (Emissions Unit 001)

None

CT1B (Emissions Unit 002)

August 22, 2012 10:58 to 11:13

Cause: Control Equipment Malfunction (loss of water injection)

Corrective Action: Water injection pump shaft sheared. CT1B was immediately shutdown and the water

injection pump was repaired.

CT2A (Emission Unit 003)

None

There were no incidents of monitor downtime for Emission Units -001, -002, or -003 during the reporting period.

There were no incidents of deviations from Title V permit requirements during the reporting period.