PM CAM Plan for EU008 (New Abrasive Blast Booth)

	Indicator 1
I. Indicator	Opacity
Measured Approach	Visible Emissions check by persons familiar with Method 9.
II. Indicator Range	While the unit is operating, an excursion is defined as the presence of **any** visible emissions. Excursions trigger an inspection, corrective action, and a report requirement.
III. Performance Criteria	
A. Data Representativeness	Measurement is being made at each emission point (cartridge type dust collector exhausts). Total of two emission points.
B. Verification of Operational Status	Not Applicable
C. QA/QC Practices and Criteria	The observer will be familiar with Reference Method 9.
D. Monitoring Frequency	Daily when the unit is operated.
E. Data Collection Procedures	The Visible Emissions observation will be recorded with the time, date, and name of observer.
F. Averaging Period	Instantaneous
G. Emission Limit	62-296.712 F.A.C. Miscellaneous Manufacturing Process Operations - Shall not cause, permit, or allow emissions of particulate matter in excess of 0.03 gr/dscf.