ACUREN

South Pierce, Florida Plant

Photo 5: Typical picture of holes in scrubber number2

Photo 6: Typical picture of erosion under one of the scrubbers

Photo 7: Typical picture of erosion on one of the Stacks