Appendix OP-1—Wet Scrubber Operating Parameters To Be Monitored and Minimum Measurement and Recording Frequencies

Operating parameters to be monitored	Minimum frequency	
	Data measurement	**Data recording**
Maximum operating parameters:		
Maximum charge rate	Continuous	1×hour
Maximum flue gas temperature	Continuous	1×minute
Minimum operating parameters:		
Minimum secondary chamber temperature	Continuous	1×minute
Minimum pressure drop across the wet scrubber or minimum horsepower or amperage to wet scrubber	Continuous	1×minute
Minimum scrubber liquor flow rate	Continuous	1×minute
Minimum scrubber liquor pH	Continuous	1×minute