COMPLIANCE PLAN FOR PULP PRODUCTION INCREASE

The construction of the blow heat recovery system was completed on October 15, 2011, but the construction of all components of the pulp dryer improvements required to achieve the 175,000 ADMT-per-year pulp production limit has not been completed. The table listed below lists the improvements which may be needed to achieve the 175,000 ADMT per year production rate and the tentative schedule date:

Task	**Tentative Completion Date**
Steam Supply and Condensate Modifications	2017-2018
Machine Fan Heater Replacements	2016-2018
Dryer Can Replacements	2013-2018
Drives an Motor Control Center	2017-2018
Oil System Filtration and Heat Exchange	2018
Improved Thread-Up System	2017
Air Supply and Exhaust Upgrades	2018
Press Hydraulic System	2016-2018
Drum Reel Replacement	2018
Lo-Vac Header Upgrade	2018
Steam Profiling Box	2018
Blend Chest Pump Upgrade	2018

These improvements must be conducted over time and during scheduled Mill annual outages.