Florida Department of Environmental Protection

Northeast District
7825 Baymeadows Way, Suite B200
Jacksonville, Florida 32256-7590
Phone: 904/807-3300 ♦ Fax: 904/448-4366

Charlie Crist
Governor

Jeff Kottkamp
Lt. Governor

Michael W. Sole
Secretary

July 20, 2007

Mr. Fred J. Perrett, General Manager
Rayonier Performance Fibers LLC
Post Office Box 2002
Fernandina Beach, Florida 32035

Nassau County – Air Permitting
Rayonier Performance Fibers LLC
AIRS ID No. 0890004
Operational Procedures for Sulfur Unloading & Spill Monitoring

Dear Mr. Perrett:

Please accept this letter as Department acknowledgement and receipt of the letter dated June 29, 2007, concerning the Molten Sulfur Unloading and Spill Monitoring procedures the Fernandina Mill established pursuant to the requirements of Rule 62-296.411(1)(h), F.A.C. (Condition F.6. of Title V Operation Permit No. 0890004-020-AV).

The Northeast District intends to reference these procedures in the Title V Operation Permit, but will not do so until the next reopening of the permit whether it is a Title V Permit Revision or Renewal.

If you have any questions regarding this matter, please call Rita Felton-Smith at (904) 807-3237.

Sincerely,

Christopher L. Kirts, P.E.
District Air Program Administrator

Cc: David Rogers, Rayonier Performance Fibers, LLC
John Gay, Compliance and Enforcement

RFS:rfs