From:	Marybeth Morrison
To:	Marybeth Morrison; Arif, Syed; Sheplak, Scott
Cc:	Lurix, Joe; Marc Bruner; Ray Schauer; Mark L. McLean; Hibbard, Cynthia; Barritt, Amber; Mohammad, Sal; sludgy@nefcobiosolids.com; whansen; Brad Vermeulen; Jim Greer; David Broten
Subject:	CORRECTION- Request for Preliminary Testing Venturi Scrubber (CAM Plan Criteria) - Impingent Tray scrubber/Cyclone Separator Retrofit Project BPF
Date:	Friday, May 03, 2013 7:31:23 AM
Importance:	High

Correction on the water flow. The test values are from 109 gpm to 0 gpm not 190 gpm. The letter has the correct value.

-----Original Message-----
From: Marybeth Morrison
Sent: Thursday, May 02, 2013 5:44 PM
To: Syed Arif; Scott Sheplak
Cc: Lurix, Joe; Marc Bruner; Ray Schauer; Mark L. McLean; Hibbard, Cynthia; Barritt, Amber; Mohammad, Sal; sludgy@nefcobiosolids.com; whansen; Brad Vermeulen; Jim Greer
Subject: Request for Preliminary Testing Venturi Scrubber (CAM Plan Criteria) - Impingent Tray scrubber/Cyclone Separator Retrofit Project BPF

Please find attached a request to perform preliminary PM/PM10 testing on the venturi scrubbers to establish CAM parameters required for the Tray Scrubber/Cyclone Separator Retrofit at the Biosolids Pelletization Facility (BPF). The Operator has proposed a range of water flows and pressure drops from 190 gpm to 0 gpm (no flow).

If you have any questions or need additional information please contact me by email or call me at (561) 640-4000 ext. 4613.

Sincerely,

Mary Beth Morrison
Environmental Programs Supervisor
Solid Waste Authority of Palm Beach County

-----Original Message-----
From: ricoh@swa.org [mailto:ricoh@swa.org]
Sent: Thursday, May 02, 2013 5:20 PM
To: Marybeth Morrison
Subject: Message from "ENVRICOH6002"

This E-mail was sent from "ENVRICOH6002" (Aficio MP 6002).

Scan Date: 05.02.2013 17:19:30 (-0400)
Queries to: ricoh@swa.org