

APPENDIX CP

COMPLIANCE PLAN FOR PULP PRODUCTION INCREASE

The construction of the blow heat recovery system was completed on October 15, 2011, but the construction of all components of the pulp dryer improvements required to achieve the 175,000 ADMT-per-year pulp production limit has not been completed. The table listed below lists the improvements which may be needed to achieve the 175,000 ADMT per year production rate and the tentative schedule date:

Task	Tentative Completion Date
Steam Supply and Condensate Modifications	2013
Machine Fan Heater Replacements	2011-2013
Dryer Can Replacements	2012-2015
Drives an Motor Control Center	2012-2015
Oil System Filtration and Heat Exchange	2013
Improved Thread-Up System	2015
Air Supply and Exhaust Upgrades	2016
Press Hydraulic System	2013
Drum Reel Replacement	2015
Lo-Vac Header Upgrade	2014
Steam Profiling Box	2015
Blend Chest Pump Upgrade	2012

These improvements must be conducted over time and during scheduled Mill annual outages.