



DAILY SUPERVISOR PAINTER VOC CHECK OFF SHEET	1 (urto	s C	ran	Hord) .		
Location: Small (North) Paint Booth		MON	TUE	WED	THUR	FRI	SAT	SUN
Compliance Item	Date	11-1	11-2	11-3	17-4-	1-1-5		
No Open Containers of Paint or VOC's		1/	1.7.	1/	1		·	
Lbs of VOC'S Improperly Disposed of				V				
Paint Filter Pressure Drop Form Completed		V	V	V.				
Filters Installed Correctly		1	レ					
Painters Last Name	Conc	nout	ereen					
Painter Trained by S/TC Environmental Regs.	-	1						
Supervisor/Group Leader Initials		CC	CC	CC				

Comments:	· ·	



Paint Filter Pressure Drop/Change Sheet

		Zero Manometer	Ad Manometer	Pressure Drop Start	Changed Filters (.3037)
Location: Small (North)	Hours of operation	(Yes)	Fluid - (Yes/No)	of Shift	(Yes/No)
Date					
Monday	16	Yes	YesNo		YesNo
Tuesday	16	Yes	Yes No		Yes/No
Wednesday	16	Yes	Yes No		YesNo
Thursday		Yes	YesNo		YesNo
Friday		Yes	Yes No		Yes No
Saturday		Yes	YesNo		YesNo
Sunday		Yes	Yes No		YesNo

Comments:				

Paint	_ ()]	()		
DAILY SUPERVISOR PAINTER VOC CHECK OFF SHEET		urt	5	-100	1)to	F ()		
Location: Large (South) Paint Booth		MON	TUE	WED	THUR	FRI	SAT	SUN
Compliance Item	Date	11-1	11-2	11-3				
No Open Containers of Paint or VOC's		11/	V	11/				
Lbs of VOC'S Improperly Disposed of		V		/				
Paint Filter Pressure Drop Form Completed		V	1	1				
Filters Installed Correctly								
Painters Last Name	1600 A	11	Taylor	-				
Painter Trained by S/TC Environmental Regs.	1.0000	100	1					
Supervisor/Group Leader Initials		60	CC	CC				

Comments:			 	•			
	· .	 				 	



Paint Filter Pressure Drop/Change Sheet

Location: Small (North)	Hours of operation	Zero Manometer (Yes)	Ad Manometer Fluid - (Yes/No)	Pressure Drop Start of Shift	Changed Filters (.3037) (Yes/No)	
Date	,					
Monday	16	Yes	YesNo		YesNo	
Tuesday	16	Yes	YesNo		Yes/No	
Wednesday	1h	Yes	Yes No		YesNo	
Thursday		Yes	YesNo		YesNo	
Friday		Yes	YesNo		YesNo	
Saturday		Yes	YesNo		YesNo	
Sunday		Yes	YesNo		YesNo	

Comments:	······································	