



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**

160 W GOVERNMENT STREET, SUITE 308
PENSACOLA, FLORIDA 32502-5740

RICK SCOTT
GOVERNOR

HERSCHEL T. VINYARD JR.
SECRETARY

November 21, 2013

Ms. Dee Thompson
Animal Services Director
Panhandle Animal Welfare Society, Inc.
752 Lovejoy Road
Fort Walton Beach, Florida 32548
deethompson@embarqmail.com

Dear Ms. Thompson:

On October 7, 2013, a Department representative with the Air Resource Management Section inspected your facility, ID 0910050. A copy of the inspection report is enclosed. The inspection and a review of Department records indicate the facility was in compliance at the time of the inspection for those items specifically noted in the inspection report.

This letter applies only to activities covered by the Air Resource Management Section. If you have any questions, please contact Chris Stoll at (850) 595-0654 or e-mail christopher.stoll@dep.state.fl.us.

Sincerely,

A handwritten signature in blue ink that reads 'Kenneth Dickey'.


Kenneth Dickey
Environmental Manager
Compliance Assurance Program

KD/cs/c

Enclosure



ANIMAL CREMATORY



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)
 RE-INSPECTION (FUI) ARMS COMPLAINT NO:

AIRS ID#: 0910050	DATE: <u>11/7/2013</u>	ARRIVE: <u>10:16 AM</u>	DEPART: <u>10:55 AM</u>
FACILITY NAME: PANHANDLE ANIMAL WELFARE-FT WALTON BEACH			
FACILITY LOCATION: 752 Lovejoy Rd NW FORT WALTON BEACH 32548-3845			
OWNER/AUTHORIZED REPRESENTATIVE: DEE THOMPSON Email: deethompson@embarqmail.com		PHONE: (850)243-1525 Mobile:	
CONTACT NAME: DEE THOMPSON Email: deethompson@embarqmail.com		PHONE: (850)243-1525 Mobile:	
ENTITLEMENT PERIOD: 1/7/2013 / 1/7/2018 (effective date) (end date)			

Facility Section

PART I: INSPECTION COMPLIANCE STATUS (check only one box)

IN COMPLIANCE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE

PART II: ONSITE INTRODUCTORY MEETING (check only one box for each question)

1. Name(s) of facility representative(s): Sam Nelson
 Brief Notes: _____

2. Is the Authorized Representative still DEE THOMPSON? ----- Yes ..No
 If no, who is?: _____
 If different, did the facility provide an administrative update within 30 days? ----- Yes ..No

3. Is the facility contact still DEE THOMPSON? ----- Yes ..No
 If no, who is?: _____

4. Will facility be conducting VE test(s) during today's inspection? ----- Yes ..No
 If yes, was the compliance authority notified at least 15 days in advance? ----- Yes ..No

Emissions Unit Section
1 –ANIMAL CREMATION INCINERATOR

PART I: FILE REVIEW PRIOR TO INSPECTION

(check only one box for each question)

1. a. Complete AC application or, if no AC permit, initial GP registration received on or after August 30, 1989? ----- Yes ..No
- b. If yes, were design calculations provided then to confirm a sufficient volume in the secondary chamber combustion zone to provide for at least a 1.0 second gas residence time at 1800 degrees Fahrenheit? ----- Yes ..No
2. Manufacturer's recommended capacity: 1500 lbs for batch unit lbs/hr for ram-charged unit.
3. Crematory unit installed after February 1, 2007? ----- Yes ..No
4. Date of last inspection: 2/15/2012
5. Past Visible Emissions (VE) tests:
- a. Was a VE test performed within each of the past 4 calendar years? ----- Yes ..No
- b. Has a VE test been performed yet within the current calendar year? ----- Yes ..No
- c. If first year of operation, was a VE test performed within 30 days of commencing operation? ----- N/A Yes ..No
- d. Date of last VE test: 3/6/2013
- e. Was the VE test report filed with the compliance authority no later than 45 days after the test? ----- Yes ..No
- f. Did the facility demonstrate compliance during the last VE test? ----- Yes ..No
- If no, what was the problem (if known)? _____

PART II: VISIBLE EMISSIONS TESTING

(check only one box for each question)

- 1. Was a visible emissions test conducted by the facility for this unit during this site visit?** ----- Yes ..No
- a. Operating capacity during test? _____ lbs for batch unit lbs/hr for ram-charged unit
- b. Was the operating capacity greater than the manufacturer's recommended capacity? ----- Yes ..No
- c. Was the test conducted with the unit operating at a capacity that is representative of normal operations? Yes ..No
- d. Was the visible emissions test conducted according to EPA Method 9? ----- Yes ..No
- e. The visible emission test resulted in an opacity of _____ % for the highest six minute average.
- f. Did the visible emission test demonstrate compliance with the limit? ----- Yes ..No
- (5% opacity, six-minute average, except that visible emissions not exceeding 15% opacity shall be allowed for up to six minutes in any one-hour)
- 2. Was a visible emissions test conducted by the inspector during this site visit?** ----- Yes ..No
- a. Operating capacity during test? _____ lbs for batch unit lbs/hr for ram-charged unit
- b. Was the operating capacity greater than the manufacturer's recommended capacity? ----- Yes ..No
- c. Was the test conducted with the unit operating at a capacity that is representative of normal operations? Yes ..No
- d. Was the visible emissions test conducted according to EPA Method 9? ----- Yes ..No
- e. The visible emission test resulted in an opacity of _____ % for the highest six minute average.
- f. Did the visible emission test demonstrate compliance with the limit? ----- Yes ..No
- (5% opacity, six-minute average, except that visible emissions not exceeding 15% opacity shall be allowed for up to six minutes in any one-hour)
- 3. Is there any reason to ask for a special test to determine compliance with the PM and CO standards?** ----- Yes ..No
- If yes, what reason? _____

PART III: MONITORING/RECORDKEEPING REQUIREMENTS

(check only one box for each question)

1. Were there any objectionable odors detected? ----- Yes ..No
An upwind/downwind survey of the facility was conducted. The observed parameters were:
Wind direction - _____ Downwind odor level detected- _____ Upwind odor level detected- _____ Scale: 1-10 (worst)
2. Continuous Monitoring Systems –
- a. Is a continuous temperature monitoring system installed on each unit to record temperatures in the secondary chamber in accordance with the manufacturer’s instructions? ----- Yes ..No
- b. Is the temperature probe properly placed, at least at the distance where the 1.0 second gas residence time at 1,800¹ 1,600² degrees was determined? ----- Yes ..No
(Application or initial notification: ¹ received on or after 8/30/89; ² received before 8/30/89)
- c. Are the following records kept on file, available for inspection, for at least the past two years?
- (1) All temperature measurements ----- Yes ..No
- (2) All continuous monitoring systems, monitoring devices, and performance testing measurements; monitoring system all continuous performance evaluations ----- Yes ..No
- (3) All CEMS or monitoring device calibration checks (last performed on _____) ----- Yes ..No
- (4) Adjustments ----- Yes ..No
- (5) Preventive maintenance performed on systems/devices ----- Yes ..No
- (6) Corrective maintenance performed on systems/devices ----- Yes ..No
- d. Are the temperature charts properly documented with operator name, operator indication of when cremation in the primary chamber was begun, date, time, and temperature markings ----- Yes ..No
- e. Was the crematory unit installed **after 2/1/07**? If no, skip e.(1) – (3) ----- Yes ..No
- (1) Is the crematory unit equipped and operated with a pollutant monitoring system to automatically control combustion based on continuous in-stack opacity measurement? ----- Yes ..No
- (2) Is the system calibrated to restrict combustion in the primary chamber whenever any opacity exceeds 15% opacity ? ----- Yes ..No
- (3) Has the opacity measurement system been cleaned and checked for proper operation in accordance with the manufacturer’s recommended maintenance schedule? ----- Yes ..No

PART IV: SECONDARY COMBUSTION ZONE TEMPERATURES

(check only one box for each question)

1. If the application to construct was **BEFORE** August 30, 1989 is the:
- a. actual operating temperature of the secondary chamber combustion zone no less than **1400°F** throughout the combustion process in the primary chamber? ----- Yes ..No
- b. secondary chamber combustion zone temperature equal to or greater than **1400°F** before the cremation process begins in the primary chamber? ----- Yes ..No
2. If the application to construct **ON** or **AFTER** August 30, 1989 is the:
- a. the actual operating temperature of the secondary chamber combustion zone no less than **1600°F** throughout the combustion process in the primary chamber? ----- Yes ..No
- b. secondary chamber combustion zone temperature equal to or greater than **1600°F** before the cremation process begins in the primary chamber? ----- Yes ..No

(check only one box for each question)

PART V: ALLOWED MATERIALS

1. Besides animal remains and, if applicable, the bedding associated with the animals and appropriate containers, are any other materials, including biomedical wastes, incinerated in the unit? ----- Yes ..No
If yes, what other materials? _____
2. Do containers contain no more than 0.5 percent by weight chlorinated plastics as certified by the manufacturer? ----- Yes ..No
If yes, is the certifying documentation from the manufacturer kept on file for at least 2 years from use? Yes ..No

(check only one box for each question)

PART VI: EQUIPMENT MAINTENANCE

1. Is the crematory unit maintained in accordance with the manufacturer's specifications? ----- Yes ..No
2. Is there a written plan onsite which addresses the operating procedures during startup, shutdown and malfunction? ----- Yes ..No
3. Does the crematory allow for a visible check on the flame characteristics? ----- Yes ..No
If no, skip a. – b.
- a. Was the flame characteristic visually checked at least once during each operating shift? ----- Yes ..No
- b. Was the flame adjusted when necessary? ----- Yes ..No

PART VII: EU INSPECTION COMPLIANCE STATUS (check only one box)

- IN COMPLIANCE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE

Facility Section (continued)

SPECIAL CONDITIONS AND PROCEDURES

(check only one box for each question)

Administrative Changes:

1. Were there any changes in the name, address, or phone number of the facility or authorized representative not associated with a change in ownership or with a physical relocation of the facility or any emissions units or operations comprising the facility; or any other similar minor administrative change at the facility? ---- Yes ..No
2. If yes, did the facility provide written notification within 30 days of the change? ----- Yes ..No

New or Modified Process Equipment or Change in Ownership:

3. Since the last registration form submittal has there been ----- Yes ..No
- a. Installation of any new process equipment? ----- Yes ..No
- b. Alterations to existing process equipment without replacement? ----- Yes ..No
- c. Replacement of existing equipment with equipment that is substantially different? ----- Yes ..No
- d. A change in ownership? ----- Yes ..No
- If the any answer to 3a. – d. is Yes , was a new registration form and the appropriate fee submitted 30 days prior to the change? ----- Yes ..No

Chris Stoll

11/7/2013

Inspector's Name (Please Print)

Date of Inspection



Inspector's Signature

11/7/2015

Approximate Date of Next Inspection

COMMENTS: On October 16, 2013 an inspection was performed at the Panhandle Animal Welfare clinic. At the time of the inspection records of preventative maintenance, adjustments, calibrations were not maintained for the months of June - September. The operator indicated that a manufacture technician had recently performed maintenance in the cremation unit, but the records of maintenance could not be provided.

On October 24, 2013, I called the facility representative, Ms. Dee Thompson, to offer compliance assistance in regards to the missing records. Ms. Thompson indicated that she would locate the records from the maintenance that was recently performed on the cremation unit and check with the operator to ensure records of preventative maintenance is being documented.

On November 7, 2013, a follow-up inspection was performed. Records were being maintained and indicate compliance with the permit limits.