

$\frac{\textbf{RECIPROCATING INTERNAL}}{\underline{\textbf{ENGINES}}} \, \frac{\textbf{COMBUSTION}}{}$



COMPLIANCE INSPECTION CHECKLIST

	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVE	• • •	
AIRS ID#: 0250769 DA	TE: <u>12/04/2012</u>	ARRIVE: 09:30AM	DEPART: <u>9:55AM</u>	
FACILITY NAME: SOUTHWEST WELLFIELD				
FACILITY LOCATION	N: 12350 80TH ST SW			
	MIAMI 33183			
OWNER/AUTHORIZE Email: terrero@miar CONTACT NAME: R Email: rorou01@mia ENTITLEMENT PERI	ICHARD O'ROURKE midade.gov	Mobile:	2: (786)552-8112 2: (786)552-8123	
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box) ☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE				
PART II: <u>CONTROL T</u>				

PART II: CONTROL TECHNOLOGY/RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (continued) (check ☑ appropriate box(es))	
	10 10 10
PART III: GENERAL CONDITIONS/MAINTENANCE REQUIREMENTS – Rule 62-210.300(4)(e)6., 8., & 12., F.A.C. (check ☑ appropriate box(es))	,
 Does the owner or operator make every reasonable effort to conduct the specific activity authorized by the general permit in a manner that minimizes adverse effects on adjacent property or on public use of the adjacent property, where applicable, and on the environment, including fish, wildlife, natural resources, water quality, or air quality?	Vo

PART IV: SPECIAL CONDITIONS AND PROCEDURE (check ☑ appropriate box(es)) A. New or Modified Process Equipment	ES – Rule 62-210.300(4)(d)4., F.A.C.			
1. Since the last inspection has there been a) installation of any new process equipment?				
MARUFUL MALIK	12/04/2012			
Inspector's Name (Please Print)	Date of Inspection	_		
	12/2013			
Inspector's Signature	Approximate Date of Next Inspection	_		

COMMENTS: On December 4, 2012 I visited this facility to conduct the annual compliance inspection. On site I met Jose R. Gonzalez, the maintenance personal of the plant located at the Radio Shop. There are four natural gas fuel engines and six diesel fuel engines at this facility. They are tested once a week. No objectionable odor was detected inside or outside of the facility.

REVIEWED

By Ray Gordon at 12:14 pm, Dec 24, 2012