

$\frac{POLYESTER}{FABRICATION} \frac{PRODUCTS}{FABRICATION}$



COMPLIANCE INSPECTION CHECKLIST

	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISC ARMS COMPLAIN	· , —		
AIRS ID#: 1030379 DATE: 6/15/10 ARRIVE: 10:10 DEPART: 10:20					
FACILITY NAME: CORINTHIAN CATAMARANS, LLC					
FACILITY LOCATION	: 1065 Island Ave				
	TARPON SPRINGS, FL	. 34689			
OWNER/AUTHORIZED REPRESENTATIVE: ROBERT MUHLHAN PHONE: (813)334-1029					
CONTACT NAME:		PE	IONE:		
ENTITLEMENT PERIOD: 9/24/2007 / 9/24/2012 (effective date) (end date)					
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box) ☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE					
 (check ☑ appropriate Does the facility of and emissions unit 62-210.300(3)(a) of (Rule 62-210.300(2)) Does the facility of not cause, suffer, a odor? Does the combined in any consecutive Does the owner/op used on a monthly Does the owner/op of at least five year Is this polyester reserved. 	perate any emissions units other its which are exempt from permitted or (b), F.A.C., or have been exempt (3)(c)5.a., F.A.C.)——————————————————————————————————	than the polyester resin p ting pursuant to the criter npted from permitting und or prohibition of subsection air pollutants which cause resin and gel-coat used ex 62-210.300(3)(c)5.c., F.A. coords to document the que c)5.d., F.A.C.)	plastic products fabrication units ia of paragraph der Rule 62-4.040, F.A.C.?	No No No No No	

PART III: CONTROL/OPERATING/MAINTENANC	E REQUIREMENTS – Rule 62-210.300, F.A.C.
(check ☑ appropriate box(es))	
involved in product fabrication on methods of reduction a) lessening the exposure of fresh resin surfaces to b) maintaining spray lay-up equipment to ensure ecomonitoring the coating thickness to avoid excess d) implementing inventory control practices to preed implementation in the entire control of the property of the property in a manner that minimizes adverse adjacent property, where applicable, and on the entire control of the property in the property in a manner that minimizes adverse adjacent property, where applicable, and on the entire control of the property in th	pollution prevention through such measures as training employees acing evaporative losses by: the air?
PART IV: SPECIAL CONDITIONS AND PROCEDUI (check ☑ appropriate box(es)) A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment?	<u>RES</u> – Rule 62-210.300(4)(d)4., F.A.C.
 c) replacement of existing equipment substantial recent notification form? d) If you answered <u>YES</u> to any of the above, did notification form and appropriate fee (Rule 6) 	d the owner submit a new and complete
Jeff Morris	6/15/10
Inspector's Name (Please Print)	Date of Inspection
	10/15/10
Inspector's Signature	Approximate Date of Next Inspection

COMMENTS: 6/15/10 - AQD discovered the facility's gate was locked. No activity was seen during the on-site inspection. A call to owner revealed that the company temporarily closed due to no work or future contracts. The owner, Robert Muhlhan, stated that he will call this office when the facility re-opens[jm]