FLORIDA	<u>S</u> C
INSPECTION TYPE:	ANNUAL (

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2)	COMPLAINT/DISCOVERY (CI)	
RE-INSPECTION (FUI)	ARMS COMPLAINT NO:	
AIRS ID#: 0112461 DATE: <u>06/17/2008</u>	ARRIVE: <u>9:00am</u> DEPART: <u>10:15am</u>	
FACILITY NAME: HARBOUR TOWNE MARINA		
FACILITY LOCATION: 801 NE 3RD AVENUE		
DANIA 33004-3401		
OWNER/AUTHORIZED REPRESENTATIVE: GARY	GROENEWOLD PHONE: (954)926-0300	
CONTACT NAME: Mike Horn	PHONE:	
ENTITLEMENT PERIOD: 8/27/2004 / 8/27/2009 (effective date) (end date)		
PART I: INSPECTION COMPLIANCE STATUS (chec		
IN COMPLIANCE MINOR Non-COMPLI	ANCE SIGNIFICANT Non-COMPLIANCE	
L		
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule (check ☑ appropriate box(es))	e 62-210.300, F.A.C.	
 Does the facility operate any emissions units other the which are exempt from permitting pursuant to the cri 		
have been exempted from permitting under Rule 62-4	I.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.) □Yes No	
2. Does the owner/operator of the facility maintain reco and the quantity of the coatings used?	Xes D No	
3. Does the owner/operator retain, and make available for of at least five years?	Xes D No	
4. Is the total quantity of VOC's in such coatings 44 lbs5. Does the amount of coatings used, include solvents at		
for cleanups?	Xes No	
PART III: <u>CONTROL/OPERATING/MAINTANANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
emission limiting standard of Chapter 62-296.500, F	ischarge of air pollutants which cause or contribute to	

PART III: <u>CONTROL/OPERATING/MAINTENANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. – (continued)

(check ☑ appropriate box(es))

3.	Does the owner/operator encourage pollution prevention through such measures as training employees
	involved in surface coating operations on methods of reducing VOC emissions by:
	a) maintaining spray coating againment to ansure affective application with a minimum of overspray?

	for the in surface counting operations on methods of reducing for the institute of	
	maintaining spray coating equipment to ensure effective application with a minimum of overspray?	
b)	monitoring the coating thickness to avoid excessive coating?	Yes No

	considering the use of low-VOC coatings (e.g., waterborne, ultra-violet cured, or powder coatings)?		
d)	implementing inventory control practices to prevent spillage?	Xes [No

d) implementing inventory control practices to prevent spillage?-----VOC emissio

e)	implementing management practices to reduce VOC emissions during cleanup by:	
	1. spraying light colored coatings before dark colored coatings to reduce the number of cleaning	
	cycles?	Yes No
	2) recycling cleaning solvents?	🛛 Yes 🗌 No
	3) using water based cleaners?	Yes No

RT IV: <u>SPECIAL CONDITIONS AND PROCEDURES</u> – Rule 62-210.300, F.A.C. A. <u>New or Modified Process Equipment</u>		
1. Since the last inspection has there been		
a) installation of any new process equipment?	Yes	No
b) alterations to existing process equipment without replacement?	Yes	No
c) replacement of existing equipment substantially different than that noted on the most		
recent notification form?	Yes	No
d) If you answered <u>YES</u> to any of the above, did the owner submit a new and complete		
notification form and appropriate fee (Rule 62-4.050, F.A.C.) to the appropriate DEP or		
local program office?	Yes	No
		_

Elizabeth F.Susky

Inspector's Name (Please Print)

06/17/2008

] No ∃ No

Date of Inspection

06/17/2009

Inspector's Signature

Approximate Date of Next Inspection

COMMENTS: In a compliance inspection conducted on 06/17/2008, AQD staff observed operations at Harbout Towne Marina. Mr. Mike Horn accompanied staff on the inspection. The facility is a large marina that services mid-size to large yachts. One section is fenced off in the yard and dedicated for boat wash out, boat bottom painting, and sanding. The yard housekeeping is excellent and they try to adhere to the Marina BMP's.

On 6/18/2008, AQD spoke to Mike Horn about his VOC usages (the facility is at 40.3/voc's/day). The facility is near its threshold for his permit. Mr. Horn mentioned that he would double check his numbers and make sure they are not reflecting purchases.