

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2)	COMPLAINT/D	OISCOVERY (CI)		
	RE-INSPECTION (FUI)	ARMS COMPLA	AINT NO:		
AIRS ID#: 0112474 DAT	E: <u>1/29/2008</u>	ARRIVE: <u>930</u>	DEPART: <u>1030</u>		
FACILITY NAME: CABLE MARINE - EAST YARD					
FACILITY LOCATION:	: 1517 SE 16TH STREET	•			
	FORT LAUDERDALE	33316-1713			
OWNER/AUTHORIZED REPRESENTATIVE: GEORGE CABLE PHONE: (954)587-4000					
CONTACT NAME:			PHONE:		
ENTITLEMENT PERIO	DD: 2/6/2005 / 2/6/2010 (effective date) (end date)				
PART I: <u>INSPECTION COMPLIANCE STATUS</u> (check ✓ only one box)					
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE					
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))					
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)					
PART III: <u>CONTROL/OPERATING/MAINTANANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))					
 Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.)					

PART III: CONTROL/OPERATING/MAINTENANCE I (check ☑ appropriate box(es))	REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued)		
cycles?2) recycling cleaning solvents?	of reducing VOC emissions by: If reducing VOC emissions by:		
PART IV: SPECIAL CONDITIONS AND PROCEDURE	EC Dula (2 210 200 E A C		
A. New or Modified Process Equipment 1. Since the last inspection has there been			
Elizabeth F.Susky	1/29/2008		
Inspector's Name (Please Print)	Date of Inspection 1/29/2008		
Inspector's Signature Approximate Date of Next Inspection			
facility has a boat pull-out, and boat hangar where bottom work inspection. The facility storage area (waste oil and paint) is lot transfer was observed and staff of Cable Marine (E) were not paint drum and mixing area was a bit messy although no paint	29/2008, AQD staff observed operations at Cable Marine East. The ork is conducted. Mr. Keith Willis (manager) was on-site during the ocated on the East side of the building. Some staining from a recent oil ified. They immediately used absorpent pads on the staining. The at was observed on the pavement just the abutting concrete wall. Two owever these do not drain anywhere and were where rebar for the old		

The facility wiil have the coporate office submit their VOC logs.