

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2)	COMPLAINT/DISCOVERY (CI)	
RE-INSPECTION (FUI)	ARMS COMPLAINT NO:	
AIRS ID#: 0112503 DATE: <u>02/24/2006</u> AF	RRIVE: <u>8:34 AM</u> DEPART: <u>9:15 AM</u>	
FACILITY NAME: SUNRISE COLLISION, INC.		
FACILITY LOCATION: 1384 NW 65TH WAY		
PLANTATION 33313		
RESPONSIBLE OFFICIAL: JOE VIVES	PHONE: (954)327-9728	
CONTACT NAME: Joe Vines	PHONE:	
REMITTANCE YEAR: ENTITLEME	NT PERIOD: 8/20/2005 / 8/20/2010 (effective date) (end date)	
	(effective date) (end date)	
PART I: INSPECTION COMPLIANCE STATUS (check	only one box)	
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE		
PART II: RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)		
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
 Is/Are the surface coating operation(s) subject to a VO emission limiting standard of Chapter 62-296.500, F.A Does the facility cause, suffer, allow or permit the disc an objectionable odor? (Rule 62.296.320(2), F.A.C.) 	.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.) Yes No harge of air pollutants which cause or contribute to	

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☐ appropriate box(es))	
ntion through such measures as training employees of reducing VOC emissions by: ffective application with a minimum of overspray? ive coating?	
ES – Rule 62-210.300, F.A.C. Yes No out replacement? Yes No ly different than that noted on the most Yes No the owner submit a new and complete 1-4.050, F.A.C.) to the appropriate DEP or Yes No	
02/24/2006	
Date of Inspection	
02/24/2007	
02/24/2007	

Mr. Vines was not at the facility during the inspection, however other staff (Tanya) accompanied AQD staff during the inspection.

Housekeeping was fair. AQD staff observed that one 55 gallon waste paint drum did not have proper capping. AQD staff spoke to staff (painter) and he immediately capped the drum. AQD staff sugessted that (in the future) a locking funnel cap would be more appropriate for the drum