

## **SURFACE COATING OPERATIONS**



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)
RE-INSPECTION (FUI) ARMS COMPLAINT NO:
AIRS ID#: 1030498 DATE: <u>6/2/10</u> ARRIVE: <u>10:15 a.m.</u> DEPART: <u>10:50 a.m.</u>
FACILITY NAME: PROTECT FINISHING
FACILITY LOCATION: SUITE M, 12900 AUTOMOBILE BLVD
CLEARWATER 33762
OWNER/AUTHORIZED REPRESENTATIVE: TOBY TENORIO PHONE: (727)572-8681
CONTACT NAME: same PHONE: (
ENTITLEMENT PERIOD: 10/19/2008 / 10/19/2013 (effective date) (end date)
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)  Yes No  2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used?————————————————————————————————————
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))
<ol> <li>Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.)</li></ol>

EQUIREMENTS – Rule 62-210.300, F.A.C. – (continued)
on through such measures as training employees reducing VOC emissions by: cetive application with a minimum of overspray? cetore coating?
S – Rule 62-210.300, F.A.C.  Yes No treplacement? Yes No different than that noted on the most Yes No e owner submit a new and complete 0.050, F.A.C.) to the appropriate DEP or Yes No
6/1/10
Date of Inspection
Date of hispection
8/1/10

**COMMENTS:** 6/3/10 - The facility did not maintain the 12-mo consecutive total since Feb, 09'. It could not be determined if the total quantity of VOC's in the coatings were 44 lbs/day or less, averaged monthly.[jm]