

$\frac{\text{POLYESTER}}{\text{FABRICATION}} \frac{\text{PRODUCTS}}{\text{FABRICATION}}$



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/D RE-INSPECTION (FUI) ARMS COMPLAINT/D	ISCOVERY (CI) AINT NO:		
AIRS ID#: 1170403 DATE: <u>03/16/2011</u> ARRIVE: <u>10:30 A</u>	AM DEPART:		
FACILITY NAME: INITIAL MARINE CORP			
FACILITY LOCATION: 650 HICKMAN CIR			
SANFORD 32771-6929			
OWNER/AUTHORIZED REPRESENTATIVE: STEVE STEPP Email: CONTACT NAME: Email: ENTITLEMENT PERIOD: 8/25/2007 / 8/25/2012 (effective date) (end date)	PHONE: (407)321-1430 Mobile: PHONE: Mobile:		
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box) ☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE PART II: CONTROL TECHNOLOGY/PECONDY/EEDING PEOUPPEMENTS — Parks (2.210.200. E.A. C.			
PART II: CONTROL TECHNOLOGY/RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))			
 Does the facility operate any emissions units other than the polyester resand emissions units which are exempt from permitting pursuant to the cr 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting (Rule 62-210.300(3)(c)5.a., F.A.C.)	riteria of paragraph g under Rule 62-4.040, F.A.C.?		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))			
1. Does the owner or operator voluntarily encourage pollution prevention through such measures as training employees involved in product fabrication on methods of reducing evaporative losses by: a) lessening the exposure of fresh resin surfaces to the air?			
 d) If you answered <u>YES</u> to any of the above, did th notification form and appropriate fee (Rule 62-4 	t replacement?different than that noted on the most	∐Yes ∐No	
local program office?		∐Yes ∐No	
Sangeeta Sharma	03/16/2011		
Inspector's Name (Please Print)	Date of Inspection	-	
Inspector's Signature	Approximate Date of Next Inspection	-	
COMMENTS: I and garry went to inspect Initial Marine Corp located at 650 Hickman Ave, Sanford Florida on 3/16/2011. Initial			

COMMENTS: I and garry went to inspect Initial Marine Corp located at 650 Hickman Ave, Sanford Florida on 3/16/2011. Initial Marine was not located at this location. Velocity boat is at this location now. We checked the backroom, and no boats were manufactured, and there was no styrene smell.