



Florida Department of Environmental Protection

Charlie Crist
Governor

Jeff Kottkamp
Lt. Governor

Michael W. Sole
Secretary

Northwest District Branch Office
630-3 Capital Circle Northeast
Tallahassee, Florida 32301

August 4, 2008

SENT VIA E-MAIL
CDSMFG@earthlink.net
CDSTJR@earthlink.net

Clayton Sembler, President
CDS Manufacturing Incorporated
106 Charles Hayes Sr. Drive
Gretna, Florida 32332

Dear Mr. Sembler:

A Department representative inspected your facility to determine compliance with the Air Quality Operating Permit. The Air Program identification number for this facility is **0390045**. Your facility permit expires on March 2, 2013. This letter applies only to activities covered by the Air Resource Management Program.

Based on the facility inspection results, the Tallahassee Branch Office reported a status of In-Compliance for your facility.

Note that your facility compliance status may be subject to further review by the District Program Office.

The assistance you provided is appreciated. You are encouraged to review the enclosed inspection checklist and its comments section. If you have any questions, your local contact is Tracy White at (850) 488-3704 or tracy.a.white@dep.state.fl.us.

Sincerely,

Marlane Castellanos
Branch Manager

MC/tw
Enclosures

cc: Rick Bradburn, FDEP, Pensacola
Mary Beth Curle, FDEP
Erica Mitchell, FDEP



CONCRETE BATCHING PLANT



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)
 RE-INSPECTION (FUI) ARMS COMPLAINT NO: _____

AIRS ID#: 0390045 **DATE:** 7/22/2008 **ARRIVE:** _____ **DEPART:** _____

FACILITY NAME: CDS-FDOT CASTING YARD

FACILITY LOCATION: 106 CHARLES HAYES SR DR
GRETNA 32332

OWNER/AUTHORIZED REPRESENTATIVE: CLAYTON SEMBLER **PHONE:** (850)875-4651

CONTACT NAME: _____ **PHONE:** _____

ENTITLEMENT PERIOD: 3/2/2008 / 3/2/2013
(effective date) (end date)

PART I: INSPECTION COMPLIANCE STATUS (check only one box)

IN COMPLIANCE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE

PART II: TESTING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414, F.A.C.
(check appropriate box(es))

Stack Emissions

- Were visible emissions tests conducted during this site visit according to EPA Method 9 (Ref.: Chapter 62-297, F.A.C.)?----- Yes No
- Are emissions from silos, weigh hoppers (batchers), and other enclosed storage and conveying equipment controlled to the extent necessary to limit visible emissions to 5 percent opacity?----- Yes No
- During visible emissions tests of the silo dust collector exhaust points was the loading of the silo conducted at a rate that is representative of the normal silo loading rate, or at least at the minimum 25 tons per hour rate, unless such rate is unachievable in practice?----- Yes No
- Are emissions from the weigh hopper (batcher) operation controlled by the silo dust collector? (If answer to this question is "Yes", then continue on to questions 4.a) and 4.b) below. If answer is "No" then skip 4.a) and 4.b) and continue on to question 5.)----- Yes No
 - Was the batching operation in operation during the visible emissions test?----- Yes No
 - During the visible emissions test, was the batching rate representative of the normal batching rate and duration?----- Yes No
- If emissions from the weigh hopper (batcher) operation are controlled by a dust collector, which is separate from the silo dust collector, are the visible emissions tests of the weigh hopper (batcher) dust collector conducted while batching at a rate that is representative of the normal batching rate and duration?----- Yes No

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414(2)(a) and (b), F.A.C. (continued)
(check appropriate box(es))

Unconfined Emissions – (Rule 62-296.320(4)(c), F.A.C.)

1. Does the owner /operator of the concrete batching plant take reasonable precautions to control unconfined emissions by:
- a) management of roads, parking areas, stock piles, and yards, which shall include one or more of the following:
 - 1) paving and maintenance of roads, parking areas, stock piles, and yards?----- Yes No
 - 2) application of water or environmentally safe dust-suppressant chemicals when necessary to control emissions?----- Yes No
 - 3) removal of particulate matter from roads and other paved areas under control of the owner/operator to re-entrainment, and from building or work areas to reduce airborne particulate matter?----- Yes No
 - 4) reduction of stock pile height, or installation of wind breaks to mitigate wind entrainment of particulate matter from stock piles?----- Yes No
 - b) use of spray bar, chute, or partial enclosure to mitigate emissions at the drop point to the truck?---- Yes No

PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300(4)(d)4., F.A.C.

A. New or Modified Process Equipment


1. Since the last inspection has there been
- a) installation of any new process equipment?----- Yes No
 - b) alterations to existing process equipment without replacement?----- Yes No
 - c) replacement of existing equipment substantially different than that noted on the most recent notification form?----- Yes No
 - d) If you answered **YES** to any of the above, did the owner submit a new and complete notification form and appropriate fee (Rule 62-4.050, FAC) to the appropriate DEP or local program office?----- Yes No

Tracy White

7/22/2008

Inspector's Name (Please Print)

Date of Inspection



Inspector's Signature

Approximate Date of Next Inspection

COMMENTS:

I met with Brian Penn, Production Supervisor. The site apparently did not have the equipment set up yet. Various silos and other concrete equipment were laying on their side and not installed. Mr. Penn said the facility would get a water truck for yard dust control. The facility was still not in operation (in regard to this permit only).

I called the main office. The Q.A. person is Tony Roberts. This report is copied to his email, as requested.

I reviewed the Department computer records. No activity records exist (compliance testing, etc.).

Note: The checklist is incomplete due to insufficient information (facility has not commenced operation).