AREA Office	e* NWD NW: PENSACOLA	County* OKALOOSA AIRS ID 0910077
Owner/Comp * Directions	MAGIC TOUCH/CHIN HO YU	Site MAGIC TOUCH
- 1	927 NE RACETRACK RD	
City* (i	T WALTON BEACH	Zip 32547 2569 Validate Address
UTM Zone [16 East 538.10 North 3368.07	Latitude 30 26 38.8068 Longitude 86 36 11.4804
Status * 🔲 🕪	ACTIVE Maj Gro	up SIC * 72 PERSONAL SERVICES
Reloc N 🔻	Shtdwn Dt Strt Dt	05/04/1998 Final Shtdwn Dt
Gov Fac * 0 No	OT OWNED OR OPERATED BY A FEDERAL, STATE, O	R LOCAL GOVE HAZ Waste Generator ID: FLD
AOR Req* N -	Ozone SIP Facility * N 🔻 Typ	e 10 PCE Drycleaning Facilities
Compliance Trackin	g · [] [Current Permit Indicator AG 🔻
Title V NON TIT	LE V non-HAP Class MINOR	HAP Class MINOR Public Exempt 🔻
# of Emis Units	C A	I Generator Rating MVV
Comment 10/22/0	8. DENEWAL TV PEDC OC AGD Denistration : Inactiv	ve per 06/24/10 e-mail from Mary Beth Curle; no perc.

**

Brynes, Marnie

From:

Brynes, Marnie

Sent:

Thursday, June 24, 2010 5:37 PM

To:

Curle, Mary Beth; Dibble, Dickson

Cc: Subject: Ajhar, Rebecca; Grant, Patricia; Mitchell, Erica; Melton, Carol; Veazey, Sandra

RE: Magic Touch Cleaners 0910077 Inspection and Request to Rescind Permit

Mary Beth-

Inactivated in ARMS.

-Marnie

From: Curle, Mary Beth

Sent: Thursday, June 24, 2010 12:51 PM To: Dibble, Dickson; Brynes, Marnie

Cc: Ajhar, Rebecca; Grant, Patricia; Mitchell, Erica; Melton, Carol

Subject: RE: Magic Touch Cleaners 0910077 Inspection and Request to Rescind Permit

Sorry, I knew that, but I had a day off and forgot EVERYTHING...

Mary Beth

From: Dibble, Dickson

Sent: Thursday, June 24, 2010 11:48 AM To: Curle, Mary Beth; Brynes, Marnie

Cc: Ajhar, Rebecca; Grant, Patricia; Mitchell, Erica; Melton, Carol

Subject: FW: Magic Touch Cleaners 0910077 Inspection and Request to Rescind Permit

Mary Beth,

Am forwarding this on to Marnie Brynes for resolution. Marnie has been trained and is currently handling all of the Perchloroethylene Dry Cleaners Air General Permit Registrations and any associated administrative issues and inquiries concerning dry cleaners.

Marnie can be reached in any one of the following ways:

Marnie.Brynes@dep.state.fl.us

Or by phone:

(850) 922-8978

Thank you and have a great day!

Dickson E. Dibble, ES III

FL Dept of Environmental Protection Div. of Air Resource Management Bureau of Air Monitoring & Mobile Sources Air General Permit Program Tel. (850) 921-9586

Dickson.Dibble@dep.state.fl.us



Please note: Florida has a very broad public records law. Most written communications to or from state officials regarding state business are public records available to the public and media upon request. Your e-mail communications may therefore be subject to public disclosure

From: Curie, Mary Beth

Sent: Thursday, June 24, 2010 12:42 PM

To: Dibble, Dickson

Cc: Mitchell, Erica; Melton, Carol

Subject: Magic Touch Cleaners 0910077 Inspection and Request to Rescind Permit

Mary Beth Curle Administrative Assistant, Northwest District Air Program 850/595-8300 x 1220; fax 850/595-8096

Please Note: Florida has a very broad public records law.

Most written communications to or from state officials regarding state business are public records available to the public and media upon request

Your e-mail communications may therefore be subject to public disclosure.



Florida Department of Environmental Protection

Northwest District 160 Governmental Center, Suite 308 Pensacola, Florida 32502-5794 Charlie Crist Governor

Jeff Kottkamp Lt. Governor

Michael W. Sole Secretary

June 24, 2010

Mr. Chin Ho Yu Magic Touch Cleaners 327 Northeast Racetrack Road Fort Walton Beach, Florida 32547

Dear Mr. Yu:

On June 17, 2010, a Department representative with the Air Resource Management Program inspected your facility, ID 0910077. A copy of the inspection report is enclosed. The inspection and a review of Department records indicate the facility was in compliance at the time of the inspection for those items specifically noted in the inspection report. Furthermore, the Department representative noted that since the perchloroethylene dry cleaning machine had been removed from the site and since the facility was no longer using perchloroethylene to clean laundry, the air general permit is no longer applicable for the facility. During the inspection you signed a statement requesting the air general permit be rescinded. This request has been forwarded to our Bureau of Air Monitoring and Mobile Sources in Tallahassee, Florida.

This letter applies only to activities covered by the Air Resource Management Program. If you have any questions, please contact Carol Melton at 850/595-8300, extension 1228 or carol.melton@dep.state.fl.us.

Sincerely,

Erica Mitchell

Ein Mitchell

Air Compliance Supervisor

EM/cm/c

Enclosure

c: Dickson Dibble, FDEP Bureau of Air Monitoring, Tallahassee



PERCHLOROETHYLENE DRY CLEANERS



COMPLIANCE INSPECTION CHECKLIST

RE-INSPECTION (FUI)	COMPLAINT/DISCOVERY (CI) ARMS COMPLAINT NO:
AIRS ID#: 0910077 DATE: 6/18/10	ARRIVE: 13:30 hrs DEPART: 13:45 hrs
FACILITY NAME: MAGIC TOUCH	
FACILITY LOCATION: 327 NE RACETRACK	CRD
FT WALTON BEACH	I 32547-2569
OWNER/AUTHORIZED REPRESENTATIVE: CH	HIN YU PHONE: (850)862-6010
CONTACT NAME: CHIN YU	PHONE: (850)862-6010
ENTITLEMENT PERIOD: 11/17/2008 / 11/17/2 (effective date) (end date)	2013
PART I: INSPECTION COMPLIANCE STATUS (·
PART II: FACILITY CLASSIFICATION - Rule 62- (check ☑ only one box in A)	213.300 FAC
A. 1. Existing small area source dry-to-dry only, x < 140 gal/yr transfer only, x < 200 gal/yr both types, x < 140 gal/yr (constructed before 12/9/91)	2. New small area source dry-to-dry only, x < 140 gal/yr transfer only, x < 200 gal/yr both types, x < 140 gal/yr (constructed on or after 12/9/91)
3. Existing large area source dry-to-dry only, $140 \le x \le 2,100$ gal/yr transfer only, $200 \le x \le 1,800$ gal/yr both types, $140 \le x \le 1,800$ gal/yr (constructed before $12/9/91$)	4. New large area source dry-to-dry only, $140 \le x \le 2,100$ gal/yr transfer only, $200 \le x \le 1,800$ gal/yr both types, $140 \le x \le 1,800$ gal/yr (constructed on or after $12/9/91$)
5. Ineligible for General Permit Arop store/out of business/petroleum facility exceeds above limits	
B. The total quantity of perchloroethylene (perc) purchased cleaning facility was 0 gallons.	urchased within the preceding 12 months by this dry

		
PA	ART III: GENERAL CONTROL REQUIREMENTS - Rule 62-213.300 FAC	(check ✓ only one box
Do	es the responsible official of the dry cleaning facility:	for each question)
1.	Store perc, and wastes containing perc, in tightly sealed & impervious containers?	□Yes □No □N/A
2.	Examine the containers for leakage?	☐Yes ☐ No ☐ N/A
3.	Close and secure machine doors except during loading/unloading?	Yes No
4.	Drain cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal?	☐Yes ☐ No ☐ N/A
	Maintain solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications?	☐Yes ☐ No ☐ N/A
PA	ART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC	
	efer to Part II-A.14. Classification: page 1 of 4, this form)	
	1. If the facility classification is a Existing small area source , no controls are requi	ired. Proceed to Part V.
	2. If the facility classification is a <u>New small area source</u> , the machine should be excondenser. Complete section A. below.	quipped with a refrigerated
	3. If the facility classification is a Existing large area source, the machine should be refrigerated condenser or a carbon adsorber. Complete both sections A and B belo must have been installed prior to September 22, 1993	
	4. If the facility classification is a <u>New large area source</u> , the machine should be eccondenser. Complete both sections A and B below.	quipped with a refrigerated
Α.	Has the responsible official of all <u>existing large area & new sources</u> :	(check ☑ only one box for each question)
1.	Equipped all machines with the appropriate vent controls?	☐Yes ☐No
2.	Equipped dry-to-dry machines with a closed-loop vapor venting system?	Yes No N/A
3.	Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door?	Yes No N/A
4.	Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis?	□Yes □No
5.	Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F?	· []Yes []No []N/A
6.	Conducted all temperature monitoring after an appropriate cool-down period and after verifying that the coolant had been completely charged?	☐Yes ☐No


PART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC (continued)	
B. Does the responsible official of an existing large or new large area source also:	(check ☑ only one box for each question)
Measure and record the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis?	□Yes □No
Measure and record the washer exhaust temperature at the condenser inlet and outlet weekly?	Yes No N/A
a) Is the temperature differential equal to, or greater than 20° F?	☐Yes ☐ No ☐ N/A
3. Measure and record the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	□Yes □ No □ N/A
a) Is the perc concentration equal to, or less than 100 ppm?	☐Yes ☐ No ☐ N/A
4. Assure that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	Yes No N/A
5. Equip transfer machines (dryers, reclaimers, and washers) with individual condenser coils?	Yes No N/A
6. Route airflow to the carbon adsorber (if used) at all times?	☐Yes ☐ No ☐ N/A
PART V: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-213.300(3) FAC	(check ☑ only one box for
Does the responsible official:	each question)
1. Maintain receipts for perc purchased?	Yes No
2. Maintain rolling monthly total of yearly perc consumption?	☐ Yes ☐ No
3. Maintain leak detection inspection and repair reports for the following:	
a) documentation of leaks repaired w/in 24 hrs? or;	Yes No N/A
b) documentation of parts ordered to repair leak and leak repaired w/in 2 days and parts installed w/in 5 days of receipt?	☐ Yes ☐ No ☐ N/A
4. Maintain calibration data? (for applicable direct reading instruments)	☐ Yes ☐ No ☐ N/A
5. Maintain exhaust duct monitoring data on perc concentrations?	☐ Yes ☐ No ☐ N/A
6. Maintain a startup/shutdown/malfunction plan?	☐ Yes ☐ No
7. Maintain deviation reports?	
a) Problem corrected?	Yes No N/A
8. Maintain a compliance plan, if applicable?	Yes No N/A

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak

(check ☑ only one box for each question)

	detection and repair inspection? Yes No
2.	Does the facility maintain a leak log?
3.	Does the responsible official check the following areas for leaks? a) Hose connections, fittings, couplings, and valves
4.	Which method(s) of detection (is/are) used by the responsible official?
**	a) Visual examination (condensed solvent on exterior surfaces)
Ca	ol Melton 6/17/10
	Inspector's Name (Please Print) Date of Inspection
/s/	
_	Inspector's Signature Approximate Date of Next Inspection

COMMENTS: Mr. Yu indicated that he no longer has a perc machine and no longer buys perc. Mr. Yu indicated that he now uses a new petroleum machine: NOVA 40. Pasted below is a picture of the new petroleum machine. Mr. Yu indicated that he sent a letter to our Tallahassee office asking them to rescind the permit. During the visit Mr. Yu signed a statement asking for his general air permit to be rescinded. Pasted below the picture is a copy of the signed statement.



New petroleum machine

detection and repair inspection? ————————————————————————————————————
3. Does the responsible official check the following areas for leaks? a) Hose connections, fittings, couplings, and valves Yes No N/A g) Muck cookers Yes No N/A
a) Hose connections, fittings, couplings, and valves
c) Filter gaskets and scating
4. Which method(s) of detection (is/are) used by the responsible official?
a) Visual examination (condensed solvent on exterior surfaces)
If using direct-reading instrumentation, is the equipment:**N/A
1) Capable of detecting perc vapor concentrations in a range of 0-500 ppm?
Inspector's Name (Please Print) Date of Inspection
Inspector's Signature Approximate Date of Next Inspection
COMMENTS:

Please rescind general air permit for 09/0077, because the Perc machine has been removed from site, and a Petroleum machine is now used.

Brynes, Marnie

From:

Brynes, Marnie

Sent:

Thursday, June 24, 2010 5:59 PM

To:

Mitchell, Erica

Cc:

Melton, Carol; Veazey, Sandra; Dibble, Dickson; Ajhar, Rebecca

Subject:

RE: Magic Tough 0910077

Erica-

Inactivated in ARMS.

-Marnie

From: Mitchell, Erica

Sent: Monday, June 21, 2010 3:42 PM

To: Brynes, Marnie **Cc:** Melton, Carol

Subject: RE: Magic Tough 0910077

Marnie,

It is my understanding that you are now handling the kind of stuff discussed below. If not, please feel free to forward this e-mail to Dickson Dibble, etc.

On June 17, 2010, a Department representative with the Air Resource Management Program inspected Magic Touch Cleaners, ID 0910077.

The Department representative noted that since the perchloroethylene dry cleaning machine had been removed from the site, and since the facility was no longer using perchloroethylene to clean laundry, the air general permit is no longer applicable for the facility.

During the inspection the Responsible Official, Chin Ho Yu, signed a statement requesting that the air general permit be rescinded.

Please rescind general air permit for 09/0077, because the Pere machine has been removed from site, and a Petroleum machine is now used.

Let me know if you need a copy of the inspection report. Please rescind the AG permit and inactivate the facility 0910077 in ARMs.

Thank you.

Erica.Mitchell@dep.state.fl.us Air Compliance Supervisor (850) 595-8300, extension 1223

From: Melton, Carol

Sent: Friday, June 18, 2010 11:38 AM

To: Mitchell, Erica

Subject: Magic Tough 0910077 2010 Insp ltr

Hi, Please review the attached. Also, please consider sending Dickson Dibble, FDEP-BAMMS, a request to rescind the air general permit for 0910077, and a request to inactivate the facility record 0910077, in ARMS. Thanks