



Department of Environmental Protection

Jeb Bush Governor Twin Towers Office Building 2600 Blair Stone Road Tallahassee, Florida 32399-2400

Colleen M. Castille Secretary

October 11, 2004

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. Hardy Johnson President, Florida Division Tarmac America, Inc. 455 Fairway Drive Deerfield Beach, Florida 33441

Re: Air Construction Permit Project No.: 0250020-016-AC Request for Revision to Air Construction Permit No.: 0250020-010-AC Tarmac Pennsuco Cement Plant, Medley, Miami-Dade County

Dear Mr. Johnson:

On September 10, 2004 the Department received your additional information for the processing of the permit application for the revision of air construction permit 0250020-010-AC. The application is still incomplete. Specifically, the following information needs clarification:

- 1. Table 2-5 "Calculation of Potential Emissions from the Kiln, Cooler, and Raw Mill Only (EU ID No. 005) Vented From the Main Stack" was submitted with the additional information. However, there does not appear to be any difference between this version of Table 2-5 and the version that was originally submitted on March 4, 2004. Were any changes actually intended to be included in this table?
- 2. The Potential PM Emission Rates for many of the baghouses have been changed from 0.01 to 0.0095 gr/dscf. Please provide justification (manufacturers' guarantees, etc.) as to why these rates were changed.

As a reminder, rule 62-4.050(3), F.A.C. requires that all applications for a Department permit must be certified by a professional engineer registered in the State of Florida. This requirement also applies to responses to Department requests for additional information of an engineering nature.

Within 45 days, please submit all requested information to me at FDEP Bureau of Air Regulation, MS 5505, 2600 Blair Stone Road, Tallahassee, FL 32399-2400. If you have any questions regarding this request for additional information, please contact me at (850) 921-9534 or Cindv.Phillips@dep.state.fl.us.

Sincerely, Cindyot, Phillips

Cindy L. Phillips, P.E. Bureau of Air Regulation

cc: Scott Quaas, Tarmac America


David A. Buff, P.E., Golder Associates

Patrick Wong, DERM

"More Protection, Less Process"



SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
■ Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. ■ Print your name and address on the reverse so that we can return the card to you. ■ Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: Mr. Hardy Johnson President, Florida Division Tarmac America, Inc. 455 Fairway Drive	A. Signature A. Signature Adjust Adjust Addressee B. Received at (Printed Name) C. Date of Delivery D. Is delivery address different from item 1? Yes If YES, enter delivery address below: No
Deerfield Beach, Florida 33441	3. Service Type Certified Mail
2 Article Number /000 16/0 00 (Transfer from service label)	013 3109 8697
PS Form 3811, August 2001 Domestic Re	eturn Receipt 102595-02-M-1540



	86.97			e e e e e e e e e e e e e e e e e e e	
	P016 E100 02	Return Receipt Fee (Endorsement Required) Restricted Delivery Fee (Endorsement Required) Total Postage & Fees	\$	Postmark Here	
· · · · · · · · · · · · · · · · · · ·		Mr™ Hardy J Florida Div	-Drive		
	4				

.

.

: .

	Types
in the same of the	and the second second
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
■ Complete Items 1, 2, and 3-Also complete) Item 4 // Restricted Delivery is desired. ■ Print your name and address on the reverse so that we can return be do to the mailplece. ■ Attach this card to the back of the mailplece. or on the front if space permits.	X Date of Deliver
1) Andre Addressed to Mr., Hardy, Johnson President, Florida Division Tarmac America, Inc. 455 Fairway Drive	D. is delivery address different from them 1? \(\text{L} \) Yes; If YES, einter delivery address below: \[\text{L} \) No.
Deerffeld Beach, Florida 3344	1. S. Service Type> [Certified Mell]
	4. Restricted Delivery? (Edna Fee)
(Iransier nom service lehel) 1 1 1 1 1 1 1 1 1	0013, 3109, 8697
'PS Foim 38.11, August 2001 "III" Domestic	Return Receipt 102565 02 44-15

·