

Transmittal memo



Air Quality
Management Division

455 Fairway Drive
Deerfield Beach, FL 33441
Environmental Department
Direct line 954.425.4165

Scott Quaas

954.480.9352

To Claire Jordahl – DERM

Date 16 Mar 2004

From

Direct fax

\_

Ref Pennsuco Cement


Tel no.


(954) 425-4165


Please find enclosed a copy of the "Flow Diagram" from the PK5 Construction Permit Revision Application; as discussed it shows the PMCD changes that the application addresses. Additionally, I have enclosed a photo of the new plant with labels of the major system components. Let me know if you need anything further.

## Confidential information

plan/wise/awinill







FLOW DIAGRAM

THE PENNSUCO - PKS

FLOWER CEM-PKS-FLOWDIAGRAM/VSD

LAST REMINION DATE 3/11/2004

Tarmac //

VIA AIRBORNE EXPRESS

BECEIAED

MAR 0 4 2004

3 March 2004

Air Quality Management Division

Ms. Mallika Muthiah Air Quality Management Division Miami-Dade Environmental Resources Management 33 SW 2<sup>nd</sup> Avenue – Suite 900 Miami, Florida 33130-1540

RE: Pennsuco Cement

Miami-Dade County – AP Air Construction Permit 0250020-010-AC

Dear Ms. Muthiah:

455 Fairway Drive
Deerfield Beach, FL 33441
(954) 481-2800
Fax (954) 421-0296
www.titanamerica.com

Environmental Services
Direct line (954) 425-4165
Direct fax (954) 480-9352
Email squaas@titanamerica.com

MAR 0 8 2004

BUREAU OF AIR REGULATION

Please find enclosed two (2) original copies of an application to modify Air Construction Permit 0250020-010-AC for the new cement plant. The application is to reflect the final engineering and actual equipment to be installed. It also is to allow retention of existing Finish Mills Nos. 1 & 2 as replacement for proposed Finish Mill No. 6 [Finish Mill No. 6 will not be installed]. Additionally, the application includes replacing the existing cement separator for Finish Mill No. 3 with a new O-Sepa separator. A revised PSD applicability analysis was completed and shows the net change in emissions of all PSD regulated pollutants is below PSD significant emission rates.

I look forward to providing any additional information you may need to expedite the review of the enclosed application. Should you have any questions or need clarification please call me at the number above.

Sincerely,

Scott Quaas

Environmental Manager

Environmental Services-Florida Business

cc: A. Townsend

D. Buff - Golder Associates

## MIAMI-DADE COUNTY, FLORIDA





ENVIRONMENTAL RESOURCES MANAGEMENT AIR QUALITY MANAGEMENT DIVISION 33 S.W. 2nd AVENUE SUITE 900 MIAMI, FLORIDA 33130-1540 TELEPHONE: (305) 372-6925 FAX: (305) 372-6954

September 16, 2004

## CERTIFIED MAIL NO. 7000 0600 0025 3504 9212 RETURN RECEIPT REQUESTED

Mr. Hardy Johnson President, Florida Division Tarmac America, LLC 455 Fairway Drive Deerfield Beach, FL 33441

Subject: Kiln 5 Startup Logs received August 26, 2004 and, Transmittal Letters with Log Sheets received August 27, 2004 for the Tarmac America, LLC Tarmac Pennsuco facility, located at, near, or in the vicinity of 11000 NW 121 Way, in Medley, Miami-Dade County, Florida. [FDEP File No. 0250020]

## Dear Mr. Johnson:

This is to bring your attention to Specific Condition No. A.13 in Air Construction Permit No. 0250020-010-AC. During a Department of Environmental Resources Management (DERM) courtesy phone call on August 26, 2004, Scott Quaas, Tarmac Environmental Manager, was advised of an impending enforcement action related to said Specific Condition. Following our phone discussion with Mr. Quaas, DERM received the above referenced documents via electronic mail submittal.

Based on staff review of the submitted documents, additional information is needed in order to make an appropriate compliance determination. Furthermore, DERM has concerns that Kiln 3 and Kiln 5 operated simultaneously in violation of Specific Condition A.13. Therefore, you are hereby advised to submit the following to our office within 7 days of receipt of this correspondence:

- 1. Explanation for the apparent simultaneous operation of Kiln 3 and Kiln 5 for the 12 days from 6/11 thru 6/22.
- 2. Log of hourly clinker production from Kiln 3 and Kiln 5 since the June 1, 2004 startup of Kiln 5.
- 3. Specific dates of introduction of kiln feed to the preheater/calciner, and the specific dates of commencement & completion of Kiln 3 shutdown.

September 16, 2004 Tarmac America, LLC File No. 0250020

- 4. 12-month rolling average ton per year emissions (SO<sub>2</sub>, NO<sub>X</sub>, CO, VOC, SAM, and PM/PM<sub>10</sub>) for the months of May, June, July and August 2004.
- 5. Log of hourly clinker production logs since August 7, 2004 (as required in Specific Condition A 13 to be submitted weekly for the 180 days after startup of Kiln 5).

If you have any questions regarding the above, please contact Claire Jordahl or myself at 305-372-6925.

Sincerely,

Mallika Muthiah, P.E., Chief

Air Facilities Section

Copy: Scott Quaas, Tarmac America, LLC, 455 Fairway Drive, Deerfield Beach, FL 33441
Alvaro Linero, P.E., Florida Department of Environmental Protection, Tallahassee, FL