

**HARDEE POWER  
PARTNERS LIMITED**

Invenergy

Via Federal Express

August 26, 2011

Ms. Danielle Henry  
Florida Department of Environmental Protection  
Southwest District Office  
13051 North Telecom Parkway  
Temple Terrace, FL 33637-0926

**RECEIVED**

**AUG 31 2011**

**DIVISION OF AIR  
RESOURCE MANAGEMENT**

Re: Hardee Power Partners Limited  
Hardee Power Station  
Title V Air Operation Permit No. 0490015-013-AV  
January – June 2011 Monitoring Report

Ms. Henry:

Pursuant to the requirements of conditions RR1 and RR4 of Appendix RR, and Condition 15 of Appendix CAM, Hardee Power Partners Limited (HPPL) hereby submits the attached semi-annual monitoring report for the Hardee Power Station for the January - June 2011 monitoring period.

Contact Matt Drennan at (863) 375-3266 ext. 227 if you have any questions regarding this information.

*I certify that, based on the information and belief formed after reasonable inquiry, the statements and information in the documents are true, accurate, and complete.*

Sincerely,



Tim Frost  
Plant Manager

Enclosure

Cc: Florida Department of Environmental Protection  
Division of Air Resource Management  
Bureau of Air Regulation  
Title V Section  
2600 Blair Stone Road, Mail Station # 5505  
Tallahassee, Florida 32399-2400

**Excursions (as defined in Table 1 of Appendix CAM) for the January - June reporting period:**

CT1B (Emissions Unit 002)

January 24, 2011 01:33 thru 01:36

Cause: Control Equipment Malfunction (insufficient water injection)

Corrective Action: None required, system self corrected and returned to proper water to fuel ratio.

---

**There were no incidents of monitor downtime for Emission Units -001, -002, or -003 during the reporting period.**

---

**There were no incidents of deviations from Title V permit requirements during the reporting period.**

---