

U.S. Postal Service
CERTIFIED MAIL RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

OFFICIAL USE

Postage	\$	Postmark Here
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		

7000 1670 0013 3109 8932

MR. DAVID BUFF, P.E.
 GOLDR ASSOCIATES, INC.
 6241 NW 23 ST, STE 500
 GAINESVILLE, FL 32653

© 2000, May 2000 See Reverse for Instructions

PLACE STICKER AT TOP OF ENVELOPE TO THE RIGHT OF RETURN ADDRESS. FOLD AT DOTTED LINE

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1 Article Addressed to:

MR. DAVID BUFF, P.E.
 GOLDR ASSOCIATES, INC.
 6241 NW 23 ST, STE 500
 GAINESVILLE, FL 32653

2 Article Number
 (Transfer from service label)

7000 1670 0013 3109 8932

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 S Friant Addressee

B. Received by (Printed Name) *S Friant* C. Date of Delivery *1/26/05*

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

UNITED STATES POSTAL SERVICE



First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

REC-10

• Sender: Please print your name, address, and ZIP+4 in this box •

JAN 31 2005

BUREAU OF AIR REGULATION

Dept of Environmental Protection
Division of Air Resources Mgt
Bureau of Air Regulation, NSR
2600 Blair Stone Rd, MS 5505
Tallahassee, FL 32399-2400



Jeb Bush
Governor

Department of Environmental Protection

Twin Towers Office Building
2600 Blair Stone Road
Tallahassee, Florida 32399-2400

Colleen M. Castille
Secretary

January 24, 2005

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Mr. David A. Buff, P.E., Q.E.P.
Golder Associates, Inc.
6241 NW 23rd Street, Suite 500
Gainesville, Florida 32653

Re: Mosaic Fertilizer, LLC
Green Bay Plant – Sulfuric Acid Plant 5 Turnaround

Dear Mr. Buff:

The Department has reviewed your request that you submitted on behalf of Mosaic Fertilizer for a determination that certain component replacement projects planned during the Sulfuric Acid Plant (SAP) 5 turnaround are not subject to Department construction permitting requirements.

The planned activities at the SAP 5 involve the following:

- Replacement of the SAP 5 water tube Waste Heat Boiler;
- Replacement of the Sulfur Burner to Waste Heat Boiler transition duct;
- Replacement of the gas duct from the Boiler to the Burner jug valve;
- Replacement of the duct from the Boiler outlet duct to the 0D Economizer;
- Replacement of the duct from the 0D Economizer to the Boiler outlet duct;
- The project will also require the existing Steam Drum be elevated, necessitating modifications to the boiler feed water piping, riser pipes, downcomers, the steam piping and the support structure and access platforms.

Please provide a process flow diagram of the plant showing the main components and highlighting the replacements to be made.

Please provide a summary of production and emissions from SAP 5 for the last two years. After we review the information, we will make a determination if these changes represent routine maintenance, repair or replacement.

If you have any questions, please call Syed Arif at (850)921-9528.

Sincerely,

James K. Pennington, P.E. Administrator
North Permitting Section

JKP/sa

cc: Jerry Kissel, DEP SWD

"More Protection, Less Process"

Printed on recycled paper.