SWD INTERNAL PERMITTING MEMORANDUM

TO:

Mara Grace Nasca

District Air Program Administrator

THRU:

Cindy Zhang-Torres, P.E. M. Jou

Air Permitting Manager

FROM:

Danny Stubbs 11,

Air Permitting Engineer

DATE:

03/11/2011

SUBJECT:

Final Permit No: 1190011-007-AO

Facility Name: Robbins Manufacturing Company

Day 90:

04/18/2011

This project is for the renewal of the operation permit for Robbins Manufacturing Company. This sawmill facility produces untreated wood products such as utility poles and lumber and includes two wood fired boilers , two kilns, a sawdust silo and a planer shaving storage bin. One of the boilers (EU ID No 002) has been shutdown since 9/6/2009 and was given a permit expiration date of 9/6/2014, which is 5 years from the date of shutdown. This is in accordance with rule 62-210.300(2)(a)3.b., F.A.C.

The enforcement status of this facility was reviewed by Mr. Jim McDonald. His comments were received via email on January 21, 2011. He commented that the facility did not have any open or closed enforcement cases within the past five years.

Mr. Malik Pickering, Ms. Brandy Flavors and I visited this facility as part of the permit renewal process on February 4, 2011 and found that the emissions units described in the permit adequately represented the equipment and processes at the plant. Mr. Pickering submitted his comments regarding the facility to me via email on February 10, 2011 and stated that he no recommended changes for the permit.

I recommend issuance of this permit.

Stubbs, Danny

From:

William Ward [wward@robbinslumber.com]

Sent:

Friday, March 11, 2011 11:44 AM

To:

Stubbs, Danny

Subject:

Hurst Boiler

The last day Hurst boiler was operational was September 6, 2009. If you need additional information please let me know. William Ward VP - Robbins

This email and any attached files are confidential and intended solely for the intended recipient(s). If you are not the named recipient you should not read, distribute, copy or alter this email. Any views or opinions expressed in this email are those of the author and do not represent those of the Wood Preserving and Manufacturing company. Warning: Although precautions have been taken to make sure no viruses are present in this email, the company cannot accept responsibility for any loss or damage that arise from the use of this email or attachments.