

Technicians Name	Scott Collier
Event Start Date	10/25/2012
Event End Date	10/25/2012
Quarter Event Starts	Q4
Quarter Event Ends	Q4
Week Event Starts	43
Week Event Ends	43
Date Report Starts	41,207
Day Occurrence Started	Thursday
Day Occurrence Ended	Thursday
Primary SSM Control Device	Primary Shut Down Start Up
Standby SSM Control Device	Not Applicable
Control Device Thiopac Component	Open Flare #5 EU #009 3000 CFM
Control Device Shut Down Selection	Malfunction
Primary Control Device Begin Shut Down Event	10/25/2012 2:39:00 AM
Primary Control Device End Of Shut Down Event	10/25/2012 2:39:00 AM
Primary Control Device End Shut Down Occurrence	10/25/2012 5:04:00 AM
Primary Control Device End Start Up Occurrence	10/25/2012 5:04:00 AM
Standby Control Device Begin Startup Event	0
Standby Control Device End Of Startup Event	0
Standby Control Device Shut Down	0
Control Device Start Up Selection	Manual Restart
Control Device Begin Start Up Event	10/25/2012 5:04:00 AM
SSM Plan Followed	Yes
Potential Emission Limitation Exceeded	None
Exceedance Selected	No
When Was There An Exceedance	None
Primary Control Device Total Hours Down For The Period	2.41666666666667
Primary Control Device Total Minutes Down For Period	145
Standby Control Device Minutes Running For Period	0
Malfunction Selection	Loss of Power
Note On Control Device Shut Down/Malfunction	FPL Power failure
Select SSM, Malfunction or Data	Control Device SSM
GCCS Component Malfunction Start Event	0
GCCS Component Malfunction End Event	0
Note on Component Malfunction	Not applicable
Component Down Time in Minutes	0
Data Review	Yes I Have Reviewed My Data
<b>Approval Status</b>	Approved