

## **HUMAN CREMATORY**



## COMPLIANCE INSPECTION CHECKLIST

ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVERY ARMS COMPLAINT NO:	(CI)	
TE: <u>06/19/2007</u>	ARRIVE: ~ 9:30 am	DEPART: ~10:45	am_
WKINS FUNERAL HOME			
135 NORTH LIME AV	/E		
SARASOTA 34236			
IAL: WAYNE HAWKINS	PHONE: (9	941)365-1767	
	PHONE:		
2007 <b>ENTIT</b>	LEMENT PERIOD: 4/14/2003 (effective date)	/ 4/14/2008 (end date)	
	EMENTS – Rule 62-296.401, F.A.C	•	
ojectionable odor(s) detected? ssions test conducted during thi			☐ Yes ⊠ No
	TE: 06/19/2007  AWKINS FUNERAL HOME  N: 135 NORTH LIME AV  SARASOTA 34236  TAL: WAYNE HAWKINS  2007  ENTITY  COMPLIANCE STATUS (compliance of the compliance	TE: 06/19/2007 ARRIVE: ~9:30 am  AWKINS FUNERAL HOME  N: 135 NORTH LIME AVE  SARASOTA 34236  FIAL: WAYNE HAWKINS PHONE: (**  2007 ENTITLEMENT PERIOD: 4/14/2003 (effective date)  ECOMPLIANCE STATUS (check only one box)  CE MINOR Non-COMPLIANCE SIGNIFICANT IS  ECORDKEEPING REQUIREMENTS – Rule 62-296.401, F.A.C (te box(es))	TE: 06/19/2007 ARRIVE: ~9:30 am DEPART: ~10:45  AWKINS FUNERAL HOME  N: 135 NORTH LIME AVE  SARASOTA 34236  PHONE: (941)365-1767  PHONE:  2007 ENTITLEMENT PERIOD: 4/14/2003 / 4/14/2008 (effective date)  [COMPLIANCE STATUS] (check only one box)  CE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE  CCORDKEEPING REQUIREMENTS – Rule 62-296.401, F.A.C.

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-296.401, F.A.C. (check ☑ appropriate box(es))	
1. Is there <b>Continuous Emissions Monitoring System</b> (CEMS) equipment installed on each unit to record temprimary and secondary chambers where there is a 1.0 second gas residence time in the secondary chamber com accordance with the manufacturer's instructions?	bustion zone in Yes No
<ul><li>a) Do temperature probes seem to be properly placed?</li><li>b) Are the following records kept on file, available for inspection for at least two years following the record measurements, maintenance, reports and records?</li></ul>	rding of such
2) Monitoring device	Yes       No         Yes       No
8) Corrective maintenance performed on systems/devices	∏Yes ☐ No
b) actual operating temperature of the secondary chamber combustion zone no less than 1400°F	⊠Yes □ No
c) cremation in the primary chamber begun after the secondary chamber combustion zone temperature	⊠Yes □ No ⊠Yes □ No
record the temperature at the point or beyond where 1.0 second gas residence time is obtained in the	□Yes □ No
<ul> <li>4. If constructed ON or AFTER August 30, 1989 is the:</li> <li>a) volume in the secondary combustion zone sufficient to provide at least a 1.0 second gas residence time @ 1800° F?</li> <li>b) the actual operating temperature of the secondary chamber combustion zone no less than 1600°F</li> </ul>	□Yes □ No
throughout the combustion process in the primary chamber?  c) secondary chamber combustion zone temperature equal to or greater than <b>1600°F</b> before the cremation process begins in the primary chamber?	☐Yes ☐ No ☐Yes ☐ No
5. Are appropriate cremation containers containing no more than 0.5 % (percent) by weight chlorinated	□Yes □ No
their use and for at least two years after their use?  b) Are there any other materials, including biomedical wastes (Rule 62-210.200, FAC) incinerated at this location?	Yes ☐ No
a) Are copies of the training certificates for all crematory operators kept on file at the facility for the durat	⊠Yes □ No tion ⊠Yes □ No

PART IV: SPECIAL CONDITIONS AND PROCEDURY A. New or Modified Process Equipment	<u>ES</u> – Rule 62-296.401, F.A.C.
1. Since the last inspection has there been	□v Mno
<ul><li>a) installation of any new process equipment?</li><li>b) alterations to existing process equipment with</li></ul>	
c) replacement of existing equipment substantiall	
recent notification form?	
d) If you answered <b>YES</b> to any of the above, did	
notification form and appropriate fee (Rule 62	2-4.050, F.A.C.) to the appropriate DEP or
local program office?	
2. If a crematory unit has been modified to the extent	
was required, have all operators been retrained to o	
3. In the case of new or modified equipment, where a required, has the owner submitted copies of all ope	
a) submitted within the 15 day required window for	
a) 0001111100 Winni III III) 1	
Debbie Telemeco-Anders, ESII	06/19/2007
Inspector's Name (Please Print)	Date of Inspection
•	•
	~ 2008
Inspector's Signature	Approximate Date of Next Inspection
	ıman boby; incinerator 1540 degrees Fahrenheir when ignited.
Constructed 1978, IEE Power Pak.	