

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)		
RE-INSPECTION (FUI) ARMS COMPLAINT NO:		
AIRS ID#: 0112091 DATE: <u>09/25/2008</u> ARRIVE: <u>10:00AM</u> DEPART: <u>10:30AM</u>		
FACILITY NAME: PHOENIX MOTORS DBA PALM COLLISION CENTER		
FACILITY LOCATION: 827 S STATE RD 7		
NORTH LAUDERDALE 33068		
OWNER/AUTHORIZED REPRESENTATIVE: KEVIN KELLEY PHONE: (954)968-4800		
CONTACT NAME: PHONE:		
ENTITLEMENT PERIOD: 6/26/2006 / 6/26/2011 (effective date) (end date)		
(**		
PART I: INSPECTION COMPLIANCE STATUS (check only one box)		
☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE		
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
 Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)		
of at least five years?		
PART III: <u>CONTROL/OPERATING/MAINTANANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
 Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.) □Yes □No Does the facility cause, suffer, allow or permit the discharge of air pollutants which cause or contribute to an objectionable odor? (Rule 62.296.320(2), F.A.C.)		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☑ appropriate box(es))		
3. Does the owner/operator encourage pollution prevention through such measures as training employees involved in surface coating operations on methods of reducing VOC emissions by: a) maintaining spray coating equipment to ensure effective application with a minimum of overspray? b) monitoring the coating thickness to avoid excessive coating?		
PART IV: <u>SPECIAL CONDITIONS AND PROCEDURES</u> – Rule 62-210.300, F.A.C. A. New or Modified Process Equipment		
Since the last inspection has there been a) installation of any new process equipment? b) alterations to existing process equipment without replace c) replacement of existing equipment substantially differen recent notification form? d) If you answered <u>YES</u> to any of the above, did the owner notification form and appropriate fee (Rule 62-4.050, F. local program office?	ement?	
Elizabeth F. Susky	09/25/2008	
Inspector's Name (Please Print)	Date of Inspection	
	09/25/2009	
Inspector's Signature	Approximate Date of Next Inspection	
COMMENTS: In compliance inspection conducted on 09/25/2008, AQD staff observed operations at Phoenix Motors DBA Palm Collision Center. Mr. Kevin Kelley (manager) accompanied staff on-site. The facility has two automotive spray booths, a mixing room and a haz-mat storage area. Housekeeping is good and both spray booths were well maintained. Mr. Kelley will be submitting VOC records from October 2007 (last inspection) to October 2008.		