



Florida Department of Environmental Protection

Charlie Crist
Governor

Jeff Kottkamp
Lt. Governor

Michael W. Sole
Secretary

Tallahassee Branch Office
630-3 Capital Circle Northeast
Tallahassee, Florida 32301

October 30, 2008

SENT VIA E-MAIL

Chumleyk@vmcmail.com

Swinyerj@vmcmail.com

Kathy Chumley
Environmental Manager
Florida Rock Industries
Route 6, Box 1403
Havana, Florida 32333

Dear Ms. Chumley:

A Department representative inspected your facility to determine compliance with the Air Quality Operating Permit. The Air Program identification number for this facility is **0730046**. The permit **expires on August 10, 2011**. This letter applies only to activities covered by the Air Resource Management Program.

Based on the facility inspection results, the Tallahassee Branch Office reported a status of In Compliance from your facility.

Note that your facility compliance status may be subject to further review by the District Program Office.

The assistance you provided is appreciated. You are encouraged to review the enclosed inspection checklist and its comments section. If you have any questions, your local contact is Tracy White at (850) 488-3704 or tracy.a.white@dep.state.fl.us.

Sincerely,

Marlane Castellanos
Branch Manager

MC/tw

Enclosures

cc: Rick Bradburn, FDEP, Pensacola
Mary Beth Curle, FDEP
Erica Mitchell, FDEP

"More Protection, Less Process"
www.dep.state.fl.us



CONCRETE BATCHING PLANT



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)
 RE-INSPECTION (FUI) ARMS COMPLAINT NO: _____

AIRS ID#: 0730046 **DATE:** 10/28/2008 **ARRIVE:** 2:00 p.m. **DEPART:** _____

FACILITY NAME: TALLAHASSEE READY-MIX & BLOCK PLANT

FACILITY LOCATION: 1872 Mills Street
TALLAHASSEE 32310

OWNER/AUTHORIZED REPRESENTATIVE: HUGH PERRY **PHONE:** (904)355-1781

CONTACT NAME: _____ **PHONE:** _____

ENTITLEMENT PERIOD: 8/10/2006 / 8/10/2011
(effective date) (end date)

PART I: INSPECTION COMPLIANCE STATUS (check only one box)

IN COMPLIANCE MINOR Non-COMPLIANCE SIGNIFICANT Non-COMPLIANCE

PART II: TESTING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414, F.A.C.
(check appropriate box(es))

Stack Emissions

- Were visible emissions tests conducted during this site visit according to EPA Method 9 (Ref.: Chapter 62-297, F.A.C.)?----- Yes No
- Are emissions from silos, weigh hoppers (batchers), and other enclosed storage and conveying equipment controlled to the extent necessary to limit visible emissions to 5 percent opacity?----- Yes No
- During visible emissions tests of the silo dust collector exhaust points was the loading of the silo conducted at a rate that is representative of the normal silo loading rate, or at least at the minimum 25 tons per hour rate, unless such rate is unachievable in practice?----- Yes No
- Are emissions from the weigh hopper (batcher) operation controlled by the silo dust collector? (If answer to this question is "Yes", then continue on to questions 4.a) and 4.b) below. If answer is "No" then skip 4.a) and 4.b) and continue on to question 5.)----- Yes No
 - Was the batching operation in operation during the visible emissions test?----- Yes No
 - During the visible emissions test, was the batching rate representative of the normal batching rate and duration?----- Yes No
- If emissions from the weigh hopper (batcher) operation are controlled by a dust collector, which is separate from the silo dust collector, are the visible emissions tests of the weigh hopper (batcher) dust collector conducted while batching at a rate that is representative of the normal batching rate and duration?----- Yes No

PART II: TESTING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414, F.A.C. – (continued)

(check appropriate box(es))

Compliance Demonstration - (Rule 62-296.401(5)(i), F.A.C.)

1. Is each dust collector exhaust point tested according to the visible emissions limiting standard as part of the annual compliance demonstration? (Rule 62-297.310(7)(a), F.A.C.)----- Yes No

New Facilities – (permitted pursuant to Rule 62-210.300(4), F.A.C., Air General Permits)

2. Did this facility demonstrate:
- a) initial compliance no later than 30 days after beginning operation?----- Yes No
- b) annual compliance within 60 days prior to each anniversary of the air general permit notification form submittal date?----- Yes No

Existing Facilities – (permitted pursuant to Rule 62-210.300(4), F.A.C., Air General Permits)

3. In order to demonstrate annual compliance, was an annual visible emissions test conducted 60 days prior to the AGP Notification form submission, and within 60 days prior to each anniversary date?----- Yes No

Test Reports – (Rules 62-213.440, F.A.C. and 62-297.310(8)(b), F.A.C.)

4. Was the required test report filed with the department as soon as practical, but no later than 45 days after the test was completed?----- Yes No

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-210.300(4)(c)2., F.A.C.

(check appropriate box(es))

1. Is this facility: 1) a stationary ; 2) a relocatable ; or does it have: 3) both, stationary and relocatable concrete batching and/or nonmetallic mineral processing plants? (*Please check only one box.*)
2. If this is a stationary concrete batching plant, is there one or more relocatable nonmetallic mineral processing plants using individual air general permits at the same location? (*If your answer to this question is YES, then proceed to questions 2.a), thru 2.d,) below.*)----- Yes No
- a) Are there any additional nonexempt units located at this facility?----- Yes No
- b) Is the total combined annual facility-wide fuel oil usage of all plants less than 240,000 gallons per calendar year?----- Yes No
- c) Is the quantity of material processed less than ten million tons per calendar year?----- Yes No
- d) Is the fuel oil sulfur content 0.5% by weight or less?----- Yes No
3. Does the owner/operator of the concrete batching plant maintain a log book or books to account for:
- a) fuel consumption on a monthly basis?----- Yes No
- b) material processed on a monthly basis?----- Yes No
- c) the sulfur content of the fuel being burned (Fuel supplier certifications)?----- Yes No

PART III: OPERATING/RECORDKEEPING REQUIREMENTS – Rule 62-296.414(2)(a) and (b), F.A.C. (continued)
(check appropriate box(es))

Unconfined Emissions – (Rule 62-296.320(4)(c), F.A.C.)

1. Does the owner /operator of the concrete batching plant take reasonable precautions to control unconfined emissions by:
- a) management of roads, parking areas, stock piles, and yards, which shall include one or more of the following:
 - 1) paving and maintenance of roads, parking areas, stock piles, and yards?----- Yes No
 - 2) application of water or environmentally safe dust-suppressant chemicals when necessary to control emissions?----- Yes No
 - 3) removal of particulate matter from roads and other paved areas under control of the owner/operator to re-entrainment, and from building or work areas to reduce airborne particulate matter?----- Yes No
 - 4) reduction of stock pile height, or installation of wind breaks to mitigate wind entrainment of particulate matter from stock piles?----- Yes No
 - b) use of spray bar, chute, or partial enclosure to mitigate emissions at the drop point to the truck?----- Yes No

PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300(4)(d)4., F.A.C.

A. New or Modified Process Equipment


1. Since the last inspection has there been
- a) installation of any new process equipment?----- Yes No
 - b) alterations to existing process equipment without replacement?----- Yes No
 - c) replacement of existing equipment substantially different than that noted on the most recent notification form?----- Yes No
 - d) If you answered **YES** to any of the above, did the owner submit a new and complete notification form and appropriate fee (Rule 62-4.050, FAC) to the appropriate DEP or local program office?----- Yes No

Tracy White

10/28/2008

Inspector's Name (Please Print)

Date of Inspection



6-12 months

Inspector's Signature

Approximate Date of Next Inspection

COMMENTS:

The purpose of this inspection was routine (annual) and also a follow up to the 8/08/2008 inspection where non compliance issues were noted.

I observed the batch point. Apparently new curtain flaps were installed on the front and back of the batch point that could be lowered manually inside the control room. New metal sheeting was added around the back hopper area to help contain emissions.

A concrete batch truck was present underneath the batch point, but the operators were not loading it (reason unknown). I went to the control room and asked the operators to lower the back flap. A button was pressed and the flap lowered into place.

I had a phone conversation with Adam Kirkland on 10/20/2008. He gave me a list of improvements, including adding concrete paving to the yard area in front of the baghouse and "new valves on the cement grate." The paving was installed.

I did not witness a loading operation during this inspection. However the facility appeared to have implemented reasonable precautions to help control dust emissions. Future annual compliance testing will be reviewed etc. to ascertain future compliance.

At this time the local Branch office will use its enforcement discretion and not pursue enforcement for the 8/08/2008 non compliance status. However, the 8/08/2008 non compliance record will remain on Department file and will be given a status of compliance without enforcement (CWOE) by the Branch office.