

# EPA VISIBLE EMISSION OBSERVATION FORM 1

Form Number	Page <u>1</u> of <u>2</u>
Continued on VEO Form Number	

Method Used (Circle One)  
 Method 203A 203B Other: \_\_\_\_\_

Company Name  
SCT Funeral Services

Facility Name

Street Address  
5500 Williamsburg Dr

City Punta Gorda State FL Zip 33951

Process Cremation Unit # 3 Operating Mode 167lbs

Control Equipment Afterburner Operating Mode 1650

Describe Emission Point  
Smallest + Southernmost stack of three stacks

Height of Emiss. Pt. Start 30ft End 30ft Height of Emiss. Pt. Rel. to Observer Start 25ft End 25ft

Distance to Emiss. Pt. Start 160ft End 160ft Direction to Emiss. Pt. (Degrees) Start 234 End 236

Vertical Angle to Obs. Pt. Start 13° End 13° Direction to Obs. Pt. (Degrees) Start 236 End 236

Distance and Direction to Observation Point from Emission Point Start 0 End 0

Describe Emissions  
Start Lighting plume End No Emissions


Emission Color Start Black End N/A Water Droplet Plume Attached  Detached  None

Describe Plume Background  
Start sky End sky

Background Color Start Blue/White End Blue/White Sky Conditions Start Scattered End Scattered

Wind Speed Start 5-16 End 5-16 Wind Direction Start S End S

Ambient Temp. Wet Bulb Temp. RH Percent



Longitude \_\_\_\_\_ Latitude \_\_\_\_\_ Declination \_\_\_\_\_

Additional Information

Min	Time Zone				Comments
	Sec	0	15	30	
1	5	10	0	0	
2	0	0	0	10	
3	10	0	5	5	
4	0	0	0	0	
5	0	0	0	0	
6	5	5	5	0	
7	0	0	0	0	
8	0	0	0	0	
9	0	0	0	0	
10	0	0	0	0	
11	0	0	0	0	
12	0	0	0	0	
13					- Temp. Check
14					
15					
16	0	0	0	0	
17	0	0	0	0	
18	0	0	0	0	
19	0	0	0	0	
20	0	0	0	0	
21	0	0	0	0	
22	0	0	0	0	
23	0	0	0	0	
24	0	0	0	0	
25	0	0	0	0	
26	0	0	0	0	
27	0	0	0	0	
28	0	0	0	0	
29	0	0	0	0	
30	0	0	0	0	

Observer's Name (Print) Sherrill Culliver

Observer's Signature Sherrill Culliver Date 4/13/09

Organization ETA DEP

Certified By ETA Date 8/09

# EPA VISIBLE EMISSION OBSERVATION FORM 1

Form Number					Page	2	Of	2
Continued on VEO Form Number								

Method Used (Circle One)			
Method 9	203A	203B	Other: _____

Company Name		
Facility Name		
Street Address		
City	State	Zip

Process	Unit #	Operating Mode
Control Equipment	Operating Mode	

Describe Emission Point			
Height of Emiss. Pt.		Height of Emiss. Pt. Rel. to Observer	
Start	End	Start	End
Distance to Emiss. Pt.		Direction to Emiss. Pt. (Degrees)	
Start	End	Start	End

Vertical Angle to Obs. Pt.		Direction to Obs. Pt. (Degrees)	
Start	End	Start	End
Distance and Direction to Observation Point from Emission Point			
Start	End		

Describe Emissions			
Start	End		
Emission Color	Water Droplet Plume		
Start	End	Attached <input type="checkbox"/>	Detached <input type="checkbox"/>
		None <input type="checkbox"/>	

Describe Plume Background			
Start	End		
Background Color	Sky Conditions		
Start	End	Start	End
Wind Speed	Wind Direction		
Start	End	Start	End
Ambient Temp.	Wet Bulb Temp.	RH Percent	
Start	End		

Source Layout Sketch

Draw North Arrow

TN  MN

Stack With Plume

Sun

Wind

Longitude	Latitude	Declination
-----------	----------	-------------

Sec Min	Time Zone				Comments
	0	15	30	45	
1	○	○	○	○	
2	○	○	○	○	
3	○	○	○	○	
4	○	○	○	○	
5	○	○	○	○	
6	○	○	○	○	
7	○	○	○	○	
8	○	○	○	○	
9	○	○	○	○	
10	○	○	○	○	
11	○	○	○	○	
12	○	○	○	○	
13	○	○	○	○	
14	○	○	○	○	
15	○	○	○	○	
16	○	○	○	○	
17	○	○	○	○	
18	○	○	○	○	
19	○	○	○	○	
20	○	○	○	○	
21	○	○	○	○	
22	○	○	○	○	
23	○	○	○	○	
24	○	○	○	○	
25	○	○	○	○	
26	○	○	○	○	
27	○	○	○	○	
28	○	○	○	○	
29	○	○	○	○	
30	○	○	○	○	

Observer's Name (Print)	
Observer's Signature	Date
Organization	
Certified By	Date

Additional Information