

PERCHLOROETHYLENE DRY CLEANERS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE :	ANNUAL (INS1, INS2)	COMPLAINT/DISCOVER	Y (CI)			
	RE-INSPECTION (FUI)	ARMS COMPLAINT NO:				
AIRS ID#: 0112278 DA	TE: <u>10/30/2009</u>	ARRIVE: 2:15PM	DEPART: <u>3:00PM</u>			
FACILITY NAME: :NU-LOOK 1 HR CLEANERS #47						
FACILITY LOCATION	N: 900 NE 62nd St					
	OAKLAND PARK 33	334-4110				
OWNER/AUTHORIZE	D REPRESENTATIVE: TER	ENCE YANG PHONE:	(954)772-6055			
CONTACT NAME:		PHONE:				
ENTITLEMENT PERIO		Facility may be operating w	ithout Entitlement!			
	(effective date) (end date)					
PART I: INSPECTION	COMPLIANCE STATUS (ch	neck 🗹 only one box)				
☐ IN COMPLIAN	CE MINOR Non-COMF	PLIANCE SIGNIFICAN	T Non-COMPLIANCE			
	CLASSIFICATION - Rule 62-2	13.300 FAC				
(check ⊻ on	ly one box in A)					
A. 1. Existing small		2. New small area source				
	aly, x < 140 gal/yr , x < 200 gal/yr	dry-to-dry only, $x < 140$ transfer only, $x < 200$ ga				
both types, x	< 140 gal/yr	both types, $x < 140 \text{ gal/y}$	yr			
(constructed l	before 12/9/91)	(constructed on or after	12/9/91)			
3. Existing larg	ge area source	4. New large area source				
dry-to-dry on	aly, $140 \le x \le 2{,}100 \text{ gal/yr}$	dry-to-dry only, $140 \le x$				
	$0.200 \le x \le 1,800 \text{ gal/yr}$ $0.40 \le x \le 1,800 \text{ gal/yr}$	transfer only, $200 \le x \le$ both types, $140 \le x \le 1$,				
	before $12/9/91$)	(constructed on or after				
5. Ineligible for General Permit						
	t of business/petroleum					
facility excee	eds above limits					
B . The total quantity of perchloroethylene (perc) purchased within the preceding 12 months by this dry						
cleaning facility	was 60 gallons.					

_						
PA	RT III: GENERAL CONTROL REQUIREMENTS – Rule 62-213.300 FAC	(check ☑ only one box				
Does the responsible official of the dry cleaning facility:			for each question)			
1.	Store perc, and wastes containing perc, in tightly sealed & impervious containers?	⊠Yes	□No	□N/A		
2.	Examine the containers for leakage?	⊠Yes	☐ No	□ N/A		
3.	Close and secure machine doors except during loading/unloading?	Yes Yes	☐ No			
4.	Drain cartridge filters in their housing or in sealed containers for at least 24 hours prior to disposal?	⊠Yes	□ No	□ N/A		
	Maintain solvent-to-carbon ratios and steam pressure for carbon adsorber beds according to the manufacturer's specifications?	⊠Yes	□ No	□ N/A		
	RT IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC efer to Part II-A.14. Classification: page 1 of 4, this form)					
	1. If the facility classification is a Existing small area source, no controls are requi	ired. Pr o	ceed to l	Part V.		
	2. If the facility classification is a <u>New small area source</u> , the machine should be excondenser. Complete section A. below.	quipped v	with a ref	rigerated		
	3. If the facility classification is a Existing large area source , the machine should be equipped with either a refrigerated condenser or a carbon adsorber. Complete both sections A and B below. Carbon adsorber must have been installed prior to September 22, 1993					
	4. If the facility classification is a <u>New large area source</u> , the machine should be econdenser. Complete both sections A and B below.	quipped v	vith a ref	rigerated		
A.	Has the responsible official of all <u>existing large</u> <u>area & new sources</u> :		only each ques	one box for stion)		
1.	Equipped all machines with the appropriate vent controls?	⊠Yes	□No			
2.	Equipped dry-to-dry machines with a closed-loop vapor venting system?	⊠Yes	□No	□N/A		
3.	Equipped the condenser with a diverter valve so airflow will be directed away from the condenser upon opening the door?	⊠Yes	□No	□N/A		
4.	Measured and recorded the temperature of the outlet exhaust stream of a refrigerated condenser on a weekly basis?	⊠Yes	□No			
5.	Repaired or adjusted the equipment within 24 hours if the exhaust temperature of the condenser exceeded 45° F?	- [Yes	□No	⊠N/A		
6.	Conducted all temperature monitoring after an appropriate cool-down period and after verifying that the coolant had been completely charged?	⊠Yes	□No			

PART IV: PROCESS VENT CONTROLS – Rule 62-213.300 FAC (continued)					
B. Does the responsible official of an existing large or new large area source also:	(check ☑ only one box for each question)				
Measure and record the exhaust temperature on the outlet side of the condenser located on dry-to-dry, reclaimer, and dryer machines on a weekly basis?	□Yes □No				
2. Measure and record the washer exhaust temperature at the condenser inlet and outlet weekly?	- □Yes □ No □N/A				
a) Is the temperature differential equal to, or greater than 20° F?	□Yes □ No □ N/A				
3. Measure and record the perc concentration in the exhaust stream weekly at the end of the final drying cycle while the machine is venting to the adsorber, if machines are equipped exclusively with a carbon adsorber?	□Yes □ No □ N/A				
a) Is the perc concentration equal to, or less than 100 ppm?	□Yes □ No □ N/A				
4. Assure that the sampling port on the carbon adsorber exhaust for measuring perc concentrations is at least 8 duct diameters downstream of any bend, contraction, or expansion; is at least 2 duct diameters upstream from any bend, contraction, or expansion; and downstream from no other inlet?	□Yes □ No □ N/A				
Equip transfer machines (dryers, reclaimers, and washers) with individual condenser coils?	- Yes No N/A				
6. Route airflow to the carbon adsorber (if used) at all times?	□Yes □ No □ N/A				
PART V: <u>RECORDKEEPING</u> <u>REQUIREMENTS</u> – Rule 62-213.300(3) FAC	(check ☑ only one box for				
Does the responsible official:	each question)				
1. Maintain receipts for perc purchased?	Yes No				
2. Maintain rolling monthly total of yearly perc consumption?	☐ Yes ☒ No				
3. Maintain leak detection inspection and repair reports for the following:					
a) documentation of leaks repaired w/in 24 hrs? or;	Yes No N/A				
b) documentation of parts ordered to repair leak and leak repaired w/in 2 days					
and parts installed w/in 5 days of receipt?	☐ Yes ☒ No ☐ N/A				
and parts installed w/in 5 days of receipt? 4. Maintain calibration data? (for applicable direct reading instruments)	 Yes				
, ,	Yes No N/A				
4. Maintain calibration data? (for applicable direct reading instruments)	 ✓ Yes ☐ No ☐ N/A ✓ Yes ☐ No ☐ N/A 				
4. Maintain calibration data? (for applicable direct reading instruments) 5. Maintain exhaust duct monitoring data on perc concentrations?	 ☐ Yes ☐ No ☐ N/A ☐ Yes ☐ No ☐ N/A ☐ Yes ☐ No 				
4. Maintain calibration data? (for applicable direct reading instruments) 5. Maintain exhaust duct monitoring data on perc concentrations? 6. Maintain a startup/shutdown/malfunction plan?	 Yes □ No □ N/A Yes □ No □ N/A Yes □ No □ Yes □ No □ N/A 				
4. Maintain calibration data? (for applicable direct reading instruments) 5. Maintain exhaust duct monitoring data on perc concentrations? 6. Maintain a startup/shutdown/malfunction plan? 7. Maintain deviation reports?					

PART VI: <u>LEAK DETECTION AND REPAIRS</u> – Rule 62-213.300 FAC

1. Does the responsible official conduct a weekly (for small sources, bi-weekly) leak

(check **☑** only one box for each question)

2. Does the facility maintain a leak log?	detection and repair inspection?	Yes No				
3. Does the responsible official check the following areas for leaks? a) Hose connections, fittings, couplings, and valves	• •	-				
a) Visual examination (condensed solvent on exterior surfaces)	3. Does the responsible official check the following areas for leaks? a) Hose connections, fittings, couplings, and valves					
Inspector's Name (Please Print) Date of Inspection 10/30/2010	4. Which method(s) of detection (is/are) used by the responsible official? a) Visual examination (condensed solvent on exterior surfaces)					
10/30/2010	Elizabeth F. Susky	10/30/2009				
	Inspector's Name (Please Print)	Date of Inspection				
Inspector's Signature Approximate Date of Next Inspection		10/30/2010				
	Inspector's Signature	Approximate Date of Next Inspection				

COMMENTS: Facility is operating with an expired entitlement and is not utilizing its DEP calendar for temperature recordings. Facility will be receiving a WN. Houskeeping was fair.