

## **SURFACE COATING OPERATIONS**



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)
RE-INSPECTION (FUI) ARMS COMPLAINT NO:
AIRS ID#: 0112316 DATE: <u>4/21/2009</u> ARRIVE: <u>1:00PM</u> DEPART: <u>2:30PM</u>
FACILITY NAME: BROWARD MARINE
FACILITY LOCATION: 750 NE 7TH AVENUE
DANIA 33004-2502
OWNER/AUTHORIZED REPRESENTATIVE: ROBERT DEAN PHONE: (954)925-8118
CONTACT NAME: Nestor Arboleda PHONE:
ENTITLEMENT PERIOD: 5/28/2005 / 5/28/2010 (effective date) (end date)
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box)
☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)
PART III: CONTROL/OPERATING/MAINTANANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))
<ol> <li>Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.) ☐ Yes ☐ No</li> <li>Does the facility cause, suffer, allow or permit the discharge of air pollutants which cause or contribute to</li> </ol>

REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued)
tion through such measures as training employees reducing VOC emissions by: fective application with a minimum of overspray?   Yes
S - Rule 62-210.300, F.A.C.
4/21/2009
Date of Inspection
NA-facility oob
t V a b - C - H -

**COMMENTS:** In a compliance inspection conducted on 4/21/2009, AQD staff observed operations at Broward Marine. Mr. Nestor Arboleda accompanied staff on the inspection. Mr. Arboleda informed AQD staff that the facility would be shutting down in a couple of months. Boats were still present on the yard, but very little activity was observed.