

$\frac{\textbf{REINFORCED POLYESTER}}{\textbf{OPERATIONS}} \, \frac{\textbf{RESIN}}{\textbf{POLYESTER}} \, \frac{\textbf{POLYESTER}}{\textbf{POLYESTER}} \, \frac{\textbf{RESIN}}{\textbf{POLYESTER}} \, \frac{\textbf{POLYESTER}}{\textbf{POLYESTER}} \, \frac{\textbf{POLY$



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVE ARMS COMPLAINT NO	· / -	
AIRS ID#: 0251093 DATE: <u>10/10/2013</u> ARRIVE: <u>10:43 AM</u> DEPART: <u>11:30 AM</u>				
FACILITY NAME: SUNRISE FIBERGLASS				
FACILITY LOCATION	3280 NW 29TH ST			
	MIAMI 33142-6308			
OWNER/AUTHORIZED REPRESENTATIVE: MINERVA MESA				
PART I: <u>INSPECTION</u> <u>COMPLIANCE</u> <u>STATUS</u> (check ✓ only one box)				
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE				
 (check ☑ appropriate Does the facility of and emissions unit 62-210.300(3)(a) of (Rule 62-210.300) Does the facility of not cause, suffer, and odor? Does the combined in any consecutive Does the owner/opused on a monthly Does the owner/opof at least five yea Is this polyester re Reasonably Availa 	perate any emissions units other ts which are exempt from permitt or (b), F.A.C., or have been exem (3)(c)5.a., F.A.C.)	than the polyester resin plastice ting pursuant to the criteria of papted from permitting under Russian probabilition of subsection 62 air pollutants which cause or corresin and gel-coat used exceed 62-210.300(3)(c)5.c., F.A.C.)-cords to document the quantity (2)5.d., F.A.C.)-ce for Department inspection, the d., F.A.C.)-ctivity subject to a volatile orgonomic permission limiting standard of	products fabrication units paragraph ale 62-4.040, F.A.C.?	

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))					
 Does the owner or operator voluntarily encourage poinvolved in product fabrication on methods of reducianal lessening the exposure of fresh resin surfaces to the maintaining spray lay-up equipment to ensure efficomonitoring the coating thickness to avoid excessing distribution in the coating the coating	the air?				
PART IV: SPECIAL CONDITIONS AND PROCEDURI (check ☑ appropriate box(es)) A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment?	ES – Rule 62-210.300(4)(d)4., F.A.C. —————————————————————————————————				
b) alterations to existing process equipment without replacement?					
FRANK DELGADO	10/10/2013				
Inspector's Name (Please Print)	Date of Inspection 10/2014				
Inspector's Signature	Approximate Date of Next Inspection				
COMMENTS: THE TWO (2) FLOOR TYPE PAINT SPRABUSINESS IS SLOW. THE HOUSEKEEPING IS POOR.	AYBOOTHS ARE USED FOR STORAGE AT THIS TIME.				

REVIEWED

By Ray Gordon at 3:31 pm, Oct 28, 2013