

## SURFACE COATING OPERATIONS



## COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE: ANNUAL (INS1, INS2) COMPLAINT/DISCOVERY (CI)		
RE-INSPECTION (FUI) ARMS COMPLAINT NO:		
AIRS ID#: 0112550 DATE: <u>2/272007</u> ARRIVE: <u>930</u> DEPART: <u>1030</u>		
FACILITY NAME: NEW ENGLAND CUSTOM WOODWORK, INC.		
FACILITY LOCATION: 933 NW 36 STREET		
OAKLAND PARK 33309		
RESPONSIBLE OFFICIAL: Stephanie Oulton PHONE: (954)564-1500		
CONTACT NAME: PHONE:		
REMITTANCE YEAR: ENTITLEMENT PERIOD: 7/16/2006 / 7/16/2011 (effective date) (end date)		
PART I: <u>INSPECTION</u> <u>COMPLIANCE</u> <u>STATUS</u> (check ✓ only one box)		
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE		
PART II: <u>RECORDKEEPING REQUIREMENTS</u> – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es))		
1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.)  2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used?		
PART III: <u>CONTROL/OPERATING/MAINTANANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C.		
(check ☐ appropriate box(es))		
<ol> <li>Is/Are the surface coating operation(s) subject to a VOC Reasonably Available Control Technology (RACT) emission limiting standard of Chapter 62-296.500, F.A.C.? (Rule 62-210.300(3)(c)4.b., F.A.C.)——————————————————————————————————</li></ol>		

PART III: CONTROL/OPERATING/MAINTENANCE REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued) (check ☑ appropriate box(es))		
3. Does the owner/operator encourage pollution prevention through such measures as training employees involved in surface coating operations on methods of reducing VOC emissions by:  a) maintaining spray coating equipment to ensure effective application with a minimum of overspray?  b) monitoring the coating thickness to avoid excessive coating?		
PART IV: SPECIAL CONDITIONS AND PROCEDURES – Rule 62-210.300, F.A.C.  A. New or Modified Process Equipment  1. Since the last inspection has there been  a) installation of any new process equipment?————————————————————————————————————		
Elizabeth F. Susky	02/27/2007	
Inspector's Name (Please Print)	Date of Inspection	
	02/27/2007	
Inspector's Signature	Approximate Date of Next Inspection	

**COMMENTS:** In a compliance inspection conducted on 2/27/2007, AQD staff observed operations at New England Custom Woodwork. The facility has a surface coating permit and has one painting spray booth ,one smaller glue side booth and a dust collector. Stephanie Oulton submitted VOC records to AQD staff during the inspection. The facility is under their threshold @ 18.53/VOC/Day. Housekeeping was good. The spray booth filters are well maintained and observed to be changed regularly. The glue side booth filters were also observed to be well-maintained and no gapping was observed.