

REINFORCED POLYESTER RESIN OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

PART III: <u>CONTROL/OPERATING/MAINTENANCE REQUIREMENTS</u> – Rule 62-210.300, F.A.C.

(check \blacksquare appropriate box(es))

1.	Does the owner or operator voluntarily encourage pollution prevention through such measures as training employees	
	involved in product fabrication on methods of reducing evaporative losses by:	
	a) lessening the exposure of fresh resin surfaces to the air? [Yes] No	
	b) maintaining spray lay-up equipment to ensure effective application with a minimum of overspray? Xes 🗌 No	
	c) monitoring the coating thickness to avoid excessive resin/get coat application? Xestimation Content of the coating thickness to avoid excessive resin/get coat application?	
	d) implementing inventory control practices to prevent spillage?	
	e) managing cleanup solvents? 🗌 Yes 🖾 No	
2.	Does the owner or operator make every reasonable effort to conduct the specific activity authorized by the	
	general permit in a manner that minimizes adverse effects on adjacent property or on public use of the	
	adjacent property, where applicable, and on the environment, including fish, wildlife, natural resources,	
	water quality, or air quality? 🛛 Yes 🗌 No	
3.	Does the owner or operator maintain the permitted facility, emission unit, or activity in good condition? 🛛 Yes 🗌 No	

PART IV: <u>SPECIAL CONDITIONS AND PROCEDURES</u> – Rule 62-210.300(4)(d)4., F.A.C. (check ☑ appropriate box(es))			
A. <u>New or Modified Process Equipment</u>			
 Since the last inspection has there been a) installation of any new process equipment? 	Yes 🖾 No		
 b) alterations to existing process equipment without replacement? c) replacement of existing equipment substantially different than that noted on the most recent notification form? 			
d) If you answered <u>YES</u> to any of the above, did the owner submit a new and complete notification form and appropriate fee (Rule 62-4.050, F.A.C.) to the appropriate DEP or local program office?	□Yes ⊠No		

//s//Michael Storino

Inspector's Name (Please Print)

12/21/2012

Date of Inspection

12/21/2013

Inspector's Signature

Approximate Date of Next Inspection

COMMENTS: Michael Storino conducted an INS2. Facility has moved from old location due to a fire June of 2011. Owner has not renewed GP. Notified and sent link for GP information via email. Facility is not maintaining gel-coat & resin purchasing records for the last 5 years or on a monthly basis. Requested last 12 months of purchase data, will provide by contacting supplier. In the future, will create a file folder and save all gel-coat/resin purchase records for inspection for 5 years.

2012 CY purchase records by product:

Gel Coat - 144 Gal CSM Styrene laminating - 55 Gal MEK Peroxide - 43 lbs Hydrex Marine High Performance laminting - 55 Gal Acetone - 560 Gal Resin - 296 Gal Styrene - 28 Gal Paint - 2 Gal, 1 Qrt Adhesive - 40z,