

$\frac{\textbf{POLYESTER}}{\textbf{FABRICATION}} \frac{\textbf{PRODUCTS}}{\textbf{FABRICATION}}$



COMPLIANCE INSPECTION CHECKLIST

	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/DISCOVERY ARMS COMPLAINT NO:	Y(CI)	
AIRS ID#: 1150152 DATE: <u>06/26/2007</u> ARRIVE: <u>~11:40 am</u> DEPA			DEPART: ~1:00 pm	
FACILITY NAME: RIVOLTA YACHTS				
FACILITY LOCATION:	2188 51st Street			
	SARASOTA 34234-			
RESPONSIBLE OFFICIAL: DAVID SCHEER		PHONE: (941)359-6590		
CONTACT NAME: David Scheer		PHONE: (941)359-6590		
REMITTANCE YEAR: 2007 ENTITLEMENT PERIOD: 10/20/2006 / 10/20/2011 (effective date) (end date)			/ 10/20/2011 (end date)	
☐ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE				
 (check ☑ appropriate Does the facility op and emissions units 62-210.300(3)(a) or (Rule 62-210.300(3) Does the facility contour cause, suffer, all odor? Does the combined in any consecutive tends of a monthly be suffered on a monthly be suffered of at least five years for the facility of the	box(es)) erate any emissions units other which are exempt from permit (b), F.A.C., or have been exen (c)5.a., F.A.C.)——————————————————————————————————	than the polyester resin plastic preting pursuant to the criteria of parampted from permitting under Rule for prohibition of subsection 62-29 air pollutants which cause or content and gel-coat used exceed 76 (62-210.300(3)(c)5.c., F.A.C.)	roducts fabrication units ragraph 62-4.040, F.A.C.?	

PART III: CONTROL/OPERATING/MAINTENANCE	REQUIREMENTS – Rule 62-210.300, F.A.C.
involved in product fabrication on methods of reduci a) lessening the exposure of fresh resin surfaces to the bymaintaining spray lay-up equipment to ensure effection monitoring the coating thickness to avoid excessing displaymenting inventory control practices to prevere eymanaging cleanup solvents?	he air?
 b) alterations to existing process equipment witho c) replacement of existing equipment substantially recent notification form? d) If you answered <u>YES</u> to any of the above, did to notification form and appropriate fee (Rule 62- 	wut replacement?
Debbie Telemeco-Anders, ESII	06/26/2007
Inspector's Name (Please Print)	Date of Inspection ~10/01/2007
Inspector's Signature	Approximate Date of Next Inspection
COMMENTS: INS 2. Debbie re-inspected the facility to a	assist in the creation of a spreadsheet they could use to track the

combined quantity of styrene containing resin and gelcoat for any 12 consecutive month period.

NOTE: Spray booth being installed for in-house wood products and gelcoat touch-up. Plan to expand glass work to next door lot.