

SURFACE COATING OPERATIONS



COMPLIANCE INSPECTION CHECKLIST

INSPECTION TYPE:	ANNUAL (INS1, INS2) RE-INSPECTION (FUI)	COMPLAINT/E ARMS COMPL	DISCOVERY (CI)		
FACILITY LOCATION	DSCIOLI YACHTING CENTER N: 3201 W SR 84 FT LAUDERDALE 33 CD REPRESENTATIVE: BOI yachting.com	33312-4817	DEPART: PHONE: (954)581-920 Mobile: PHONE: (954)581-920	00	
Email: ENTITLEMENT PERIO		4	Mobile: (954)381-920	70	
PART I: INSPECTION COMPLIANCE STATUS (check ☑ only one box) ☑ IN COMPLIANCE ☐ MINOR Non-COMPLIANCE ☐ SIGNIFICANT Non-COMPLIANCE					
PART II: RECORDKEEPING REQUIREMENTS – Rule 62-210.300, F.A.C. (check ☑ appropriate box(es)) 1. Does the facility operate any emissions units other than the surface coating operations and emissions units which are exempt from permitting pursuant to the criteria of paragraph 62-210.300(3)(a) or (b), F.A.C., or have been exempted from permitting under Rule 62-4.040, F.A.C.? (Rule 62-210.300(3)(c)4.a., F.A.C.) ☐ Yes ☐ No 2. Does the owner/operator of the facility maintain records to document the VOC content of the coatings and the quantity of the coatings used? ☐ No 3. Does the owner/operator retain, and make available for Department inspection, these records for a period of at least five years? ☐ No 4. Is the total quantity of VOC's in such coatings 44 lbs/day or less, averaged monthly? ☐ Yes ☐ No 5. Does the amount of coatings used, include solvents and thinners used in the process including those used for cleanups? ☐ No					
 (check ☑ appropriate Is/Are the surface emission limiting Does the facility 	(OPERATING/MAINTANAN) the box(es)) the coating operation(s) subject to g standard of Chapter 62-296.50 the cause, suffer, allow or permit the codor? (Rule 62-296.320(2)) F.A.	o a VOC Reasonably A 00, F.A.C.? (Rule 62-2 he discharge of air poll	Available Control Technolo 10.300(3)(c)4.b., F.A.C.) lutants which cause or cont	ogy (RACT)	

PART III: CONTROL/OPERATING/MAINTENANCE (check ☑ appropriate box(es))	REQUIREMENTS – Rule 62-210.300, F.A.C. – (continued)
cycles? 2) recycling cleaning solvents?	freducing VOC emissions by: ffective application with a minimum of overspray? ive coating?
PART IV: SPECIAL CONDITIONS AND PROCEDURE A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment? b) alterations to existing process equipment witho c) replacement of existing equipment substantially recent notification form? d) If you answered YES to any of the above, did to notification form and appropriate fee (Rule 62-local program office?	out replacement? yes No y different than that noted on the most
A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment? b) alterations to existing process equipment witho c) replacement of existing equipment substantially recent notification form? d) If you answered YES to any of the above, did to notification form and appropriate fee (Rule 62-	out replacement? yes No y different than that noted on the most
A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment? b) alterations to existing process equipment witho c) replacement of existing equipment substantially recent notification form? d) If you answered YES to any of the above, did to notification form and appropriate fee (Rule 62-local program office?	
A. New or Modified Process Equipment 1. Since the last inspection has there been a) installation of any new process equipment? b) alterations to existing process equipment witho c) replacement of existing equipment substantially recent notification form? d) If you answered YES to any of the above, did to notification form and appropriate fee (Rule 62-local program office?	out replacement?

COMMENTS: In a compliance inspection conducted on 11/1/2011, AQD staff observed operations at Roscioli Marine. Mr. John Slate (Manager) accompanied staff on the inpsection. This facility is a boat marina that has large hangars for bottom work and maintenance/repair on boats. They also conduct small amounts of resin work for patching and smaller marine parts.