



RECEIVED

AUG 20 2012

DIVISION OF AIR
RESOURCE MANAGEMENT

August 15, 2012

Florida Department of Environmental Protection
Division of Air Resource Management
2600 Blair Stone Road, MS 5500
Tallahassee, FL 32399

RE: APAC - Southeast, Inc. Melbourne Asphalt Plant Status Update
(Facility ID 0090049)

To Whom It May Concern,

The APAC - Southeast, Inc. Melbourne Asphalt Plant site has not operated since November of 2011 when plant was abruptly idled due to a lack of demand for asphalt in the area. The site is not anticipated to operate during the remainder of the 2012 Federal Fiscal Year (FFY). We are requesting DEP to update the site's operational status to "Long-Term Reserve Shutdown" and agree to waive the site's annual Method 5 and 9 compliance testing requirements for the 2012 FFY.

Testing of the asphalt plant will be completed as soon as practicable but no later than 30 days after the facility resumes operations.

A relocated RAP crushing unit has not operated, and is not anticipated to operate, at the site during the 2012 FFY. A current Method 9 test report will be submitted to the Department upon resuming crushing operations at the site.

Please contact Erin Zimmet at Erin.Zimmet@oldcastlematerials.com or 386-257-5504 ext. 221 with any questions regarding this submission.

Thank you,

A handwritten signature in black ink, appearing to read 'Mark Marine', written in a cursive style.

Mark Marine
President, APAC - Southeast, Inc.