

**RECEIVED**

MAY 16 2002

BUREAU OF AIR REGULATION

May 14, 2002

Ms. Cindy Phillips, P.E.  
FDEP Bureau of Air Regulation  
MS 5505  
2600 Blair Stone Road  
Tallahassee, FL 32399-2400

SUBJECT: Title V Air Operation Permit No. 0230035-001-AV  
112(j) notification  
TIMCO, Lake City Airport, Columbia County

Dear Ms. Phillips,

Please be advised that TIMCO is a facility conducting aircraft maintenance and repair for independent customers in eight hangars. Our facility may fall into the Reciprocating Internal Combustion Engine source category due to the existence of diesel-powered engines which power our emergency fire control system water pumps. These pumps are only activated for weekly testing and would only otherwise be in use in the event of a fire.

If you have any questions, please contact Jim Pestrak at (386) 758-3000, extension 254.

Sincerely,

Dale Mullinax  
VP/General Manager  
TIMCO-Lake City


Cc: EPA-Region 4

**TIMCO**

Rt. 19 Box 1029  
Lake City, FL 32025  
FAA Repair Station DU4R141M



7001 1940 0001 7450 2236



*Ms. Andy Phillips, P.E.,  
FDEP Bureau of Air Regulation  
MS. 5505  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400*

**RETURN RECEIPT  
REQUESTED**

32399+6542

