3080		MAIL REC	Coverage Provided)	
111	rir. James r	i. Chansiel, i	·Li., D.I.A.	
0021 6524	Postage Certified Fee Return Receipt Fee (Endorsement Required) Restricted Delivery Fee (Endorsement Required)	\$	Postmark Here	
	Total Postage & Fees	L <del>'</del>		
90. 0002	Mr. James N Street, Apt. No.; or PO Bi 21 West Chu	y) (to be completed by mai M. Chansler, l ox No. irch Street Florida 322	P.E., D.P.A.	
!	PS Form 3800, July 1999		See Reverse for Instructions	3. 2.

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<ul> <li>Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.</li> <li>Print your name and address on the reverse so that we can return the card to you.</li> <li>Attach this card to the back of the mailpiece, or on the front if space permits.</li> <li>Article Addressed to:         <ul> <li>Mr. James M. Chansler, P.E.,</li> <li>D.P.A.</li> </ul> </li> <li>V.P., Operations and Maintenance and Responsible Official</li> </ul>	A. Received by (Please Purifically)  C. Signature  X
JEA 21 West Church Street Jacksonville, Florida 32202	3. Service Type





## Department of Environmental Protection

Jeb Bush Governor Twin Towers Office Building 2600 Blair Stone Road Tallahassee, Florida 32399-2400

David B. Struhs Secretary

September 18, 2002

CERTIFIED MAIL - Return Receipt Requested

Mr. James M. Chansler, P.E., D.P.A. V.P., Operations and Maintenance and Responsible Official JEA 21 West Church Street Jacksonville, FL 32202

Re:

ı

Title V Air Operation Permit Revision Application

Northside Generating Station

Permit Project No.: 0310045-010-AV

Facility ID: 0310045

Nos. 1 and 2 Circulating Fluidized Bed Boilers

Dear Mr. Chansler:

The Department has received the application for revision on August 9, 2002, for the incorporation of the repowering project at JEA's Northside Generating Station. Based on our initial review of the proposed project, we have determined that additional information is needed in order to continue processing this application package. Please provide all assumptions, calculations, and reference material(s), that are used or reflected in any of your responses to the following issues:

1. Based on the initial performance testing conducted May 20 and 21, 2002, pursuant to 40 CFR 60.8, the particulate matter (PM) filter catches were less than 50 mgs during the 3 (three) 1-hr tests. Therefore, and per the Department's conversations with the U.S. EPA, Region 4, the subsequesnt initial compliance tests for all PM test runs will have to be conducted for a minimum duration of 120 minutes pursuant to 40 CR 60, Subpart Da. Once the test results have been received and compliance demonstrated, we will resume permitting of the request.

If you have any questions, please contact Bruce Mitchell at 850/413-9198.

Sincerely,

A. A. Linero, P.E.

Bureau of Air Regulation

cc: Bert Gianazza, P.E., JEA Chris Kirts, DEP - NED